

THE DOWNERS AT ICA STREET

ACTED DISTRICT CHACG

THE RESERVE CHACGE

ACTED CONTROL

ACTED CONTRO

BRADENHI AD TEST REPORT

MARKET SURFER OF ASSESSED.

Diate of Test 9-7-25 Weeks	Mer #30-007-20759	
Property Name VPR B Well No.	64 Location: Unit MSection 19 Township 29N Range 198	
	ubing O Intermediate NACasing Bradenhead 6	
	TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE	
TIME 5 min D	Steady Flow	
10 min 0 11	Surges	
15 min (2)	Down to Nothing	
20 min	Nothing	
25 min	Gas	
30 min /	Gas & Water	
	Water	
If bradenhead flowed water, check all of the description		
CLEAR FRESH SALTY		
5 MINUTE SHUT-IN PRESSURE BRADENHEAD D INTERMEDIATE NA		
REMARKS: Brades head notified		
- Hothing after 5 min		
By Nike Fanelli W	itness	
operator (Position)	itness	
E-mail address		

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

Condition

None

Created

By smcfall

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 507488

Condition Date

10/16/2025

CONDITIONS

Operator:	OGRID:
Wapiti Operating, LLC	328741
1251 Lumpkin Rd	Action Number:
Houston, TX 77043	507488
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)
CONDITIONS	

Released to Imaging: 10/16/2025 4:25:47 PM