

OIL DONSERVATION DIMBION
AZTEC DISTRICT DEPICE
1000 RIG BRAZOS ROAC
AZTEC NM 87440
1505(13046713 RAX 1308 TUALS
http://dam.nrd.stata.nm.us/pod/District/Tualfilis/Tual

BRADINHIAD IEST REPORT

THEFT I I DIE IN A SERVE.

Date of Test 9-7-25 Open	API#36-607-20764
Property Name VPR 13 Well No.	138 Location: Unit O Section 13 Township 1921 Range 188
Well Status(Shut-In or Producing) Initial PSI:	Tubing D Intermediate NACasing 10 Bradenhead 0
OPEN BRADENHEAD AND INTERMEDIAT	E TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg TIME	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
5 min D	Steady Flow
10 min 0 11	Surges
15 min 0 11	Down to Nothing
20 min	Nothing X
25 min	Gas
30 min	Gas & Water
	Water
If bradenhead flowed water, check all of the description	
CLEARFRESHSALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADENHE	EAD O INTERMEDIATE NA
REMARKS: Braden mend - D	
- O-after 5 min	
Decator ((Postion)	Witness
E-mail address	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 507493

CONDITIONS

Operator:	OGRID:
Wapiti Operating, LLC	328741
1251 Lumpkin Rd	Action Number:
Houston, TX 77043	507493
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
smcfall	None	10/16/2025