

AL DONSERVATION DIVISION
ACTED DISTRICT OFFICE
1600 RIG BRAZOS ROAD
AZTEC NM STATO
568-334-8-72 FAX 1580-301-6
http://doi.org/10.1001/j.stato.up/1

BRADINHIAD TEST REPORT

					and a Figure Figure	E BUREAU		
la E	Las		9-19	-25	Operator Loc	piti API	#36-607.20780	
							1 20 Township 21 Range	9
Well	S tatus(Shut-	In or Prod	ucing) Initial	PSI: Tubing 6 I	ntermediate_w/\(\)	Casing (Bradenhead O	l
							LLY FOR 15 MINUTES EAC	
Testing	BH		PRESSU enhead Csg				ARACTERISTICS	
TIME 5 min_	0		10		Steady Flor	λ		
10 min_	0.		10					
15 min_	0		10		Down to No	othing		
20 min_					Nothing_	×		
25 min_		-(-			Gas			
30 min_								
If braden	head fl	owed v	vater, chec	k all of the desc	riptions that apply be	low:		
(CLEAR_		FRESH_	SALTY	SULFUR_	BLACK		
5 MINUT	E SHU	T-IN F	RESSURE	E BRADE	ENHEAD O	INTERMEDIAT	E NIA	
REMARK	.S:			0-0				
_	00	Str.	er 5	min				
By M	Ke T	Tap	elli		Witness_			
0,5	sition)	TOP	1					

E-mail address ____

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 515062

CONDITIONS

Operator:	OGRID:
Wapiti Operating, LLC	328741
1251 Lumpkin Rd	Action Number:
Houston, TX 77043	515062
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
smcfall	None	10/16/2025