

Well Name: SAN JUAN 28-7 UNIT	Well Location: T27N / R7W / SEC 28 / NWNE / 36.54828 / -107.57718	County or Parish/State: RIO ARriba / NM
Well Number: 217	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMSF078640	Unit or CA Name:	Unit or CA Number:
US Well Number: 3003920972	Operator: HILCORP ENERGY COMPANY	

Subsequent Report

Sundry ID: 2877567

Type of Submission: Subsequent Report	Type of Action: Mechanical Integrity Test
Date Sundry Submitted: 10/08/2025	Time Sundry Submitted: 09:11
Date Operation Actually Began: 10/07/2025	

Actual Procedure: MIT test performed on the subject well on 10/07/2025. PT to 560# for 30min, test good. Witnessed by Jason Heslop with NMOCD. Please see attached chart. Hilcorp requests OCD's permission to extend the Temporarily abandoned status to review for future potential.

SR Attachments

Actual Procedure

- Current_Schematic___SAN_JUAN_28_7_UNIT_217_2025_07_18_20251008091052.pdf
- MIT_Report_SJU_28_7_217_10_7_25_20251008091035.pdf
- MIT_Chart_SJU_28_7_217_10_7_25_20251008091025.pdf

Well Name: SAN JUAN 28-7 UNIT	Well Location: T27N / R7W / SEC 28 / NWNE / 36.54828 / -107.57718	County or Parish/State: RIO ARRIBA / NM
Well Number: 217	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMSF078640	Unit or CA Name:	Unit or CA Number:
US Well Number: 3003920972	Operator: HILCORP ENERGY COMPANY	

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TAMMY JONES	Signed on: OCT 08, 2025 09:11 AM
Name: HILCORP ENERGY COMPANY	
Title: Regulatory Compliance Specialist	
Street Address: 382 ROAD 3100	
City: AZTEC	State: NM
Phone: (505) 324-5185	
Email address: TAJONES@HILCORP.COM	

Field

Representative Name:		
Street Address:		
City:	State:	Zip:
Phone:		
Email address:		

BLM Point of Contact

BLM POC Name: KENNETH G RENNICK	BLM POC Title: Petroleum Engineer
BLM POC Phone: 5055647742	BLM POC Email Address: krennick@blm.gov
Disposition: Accepted	Disposition Date: 10/14/2025
Signature: Kenneth Rennick	



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 10-7-25 Operator Hilcorp API # 30-039-20972
 Property Name San Juan 28 7 Well # Unit 217 Location: Unit B Sec 28 Twn 27N Rge D7W
 Land Type: State _____ Well Type: _____
 Federal X Water Injection _____
 Private _____ Salt Water Disposal _____
 Indian _____ Gas Injection _____
 Producing Oil/Gas (Gas)
 Pressure observation _____

Temporarily Abandoned Well (Y) TA Expires: This well was TA 11/16/2010

Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
 Bradenhead Pres. 0 Tbg. Inj. Pres. _____
 Tubing Pres. 0
 Int. Casing Pres. _____

Pressured annulus up to 560 psi. for 20 mins. Test (passed) failed

REMARKS: There is no tubing in this well. Pressured casing to 560
5 min - 560 casing, BH-O. 10 - min - 560 casing, BH-O. 15 min - 560 casing BH-O.
20 - min 558 - casing BH-O. 25 - min 558 - casing BH-O. 30 min 558 - casing BH-O.
Pressure was constant at the end. Bled pressure off to zero.
Bridge plug at 3060
Pressure chart certified 6/24/25

By Ted Bear Witness Jason Heslop
 (Operator Representative) (NMOCD)
Wellsite Supervisor
 (Position)

Revised 02-11-02



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-7-25 Operator Hilcorp API #30-039-20972

Property Name San Juan 2897 Well No. Unit 217 Location: Unit 3 Section 20 Township 27N Range 07W

Well Status (Shut-In) or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	0		0		
10 min	0		0		
15 min	0		0		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

The tubing has been removed from this well which is in TA status.
Gauge on BH was 0. Opened valve to nothing. No change in status
the entire test. Shut in BH for 5 minutes, opened to nothing

By Tel Baird
Wellsite Supervisor
(Position)

Witness San Diego Jason Heslop
NMCD

E-mail address tel.baird@hilcorp.com

Hikorp
Sec 28-Twn 027N-Rng 007W
API 30-039-20972

45

50

55

60

5

10

15


20

25

30

35

40



PRINTED IN U.S.A.




Current Schematic - Version 3

Well Name: SAN JUAN 28-7 UNIT #217

API / UWI 3003920972	Surface Legal Location 028-027N-007W-B	Field Name CH/DK COM	Route 0906	State/Province NEW MEXICO	Well Configuration Type Vertical
Ground Elevation (ft) 6,534.00	Original KB/RT Elevation (ft) 6,544.00	Tubing Hanger Elevation (ft) 6,534.00	RKB to GL (ft) 10.00	KB-Casing Flange Distance (ft) 10.00	KB-Tubing Hanger Distance (ft) 10.00
Tubing Strings					
Run Date 8/10/2006 14:00	Set Depth (ftKB) 5,182.17	String Max Nominal OD (in) 2 3/8	String Min Nominal ID (in) 2.00	Weight/Length (lb/ft) 4.60	Original Spud Date 7/30/1978 00:00

Original Hole, SAN JUAN 28-7 UNIT #217 [Vertical]





SIGN-INHELP

SearchesOperator DataHearing Fee Application

OCD Permitting

HomeError Notification

An Unexpected Error Has Occurred

Please restart your browser and try to complete this action again. If you continue to experience this issue please contact an OCD representative.

Thank you.

New Mexico Energy, Minerals and Natural Resources Department | Copyright 2012
1220 South St. Francis Drive | Santa Fe, NM 87505 | P: (505) 476-3200 | F: (505) 476-3220

emnrd

EMNRD HomeOCD Main PageOCD RulesHelp