## Sundry Print Report

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Well Name: POKER LAKE UNIT 21 BD Well Location: T25S / R30E / SEC 21 /

SESE / 32.109862 / -103.880002

County or Parish/State: EDDY /

NM

Well Number: 907H Type of Well: OIL WELL Allottee or Tribe Name:

Lease Number: NMNM0005039A,

NMNM05039A

Unit or CA Name: DONOTUSE, POKER

LAKE UNIT

Unit or CA Number: NMNM071016Z, NMNM71016X

**US Well Number:** 3001545701 **Operator:** XTO PERMIAN OPERATING

LLC

### **Subsequent Report**

Type of Submission: Subsequent Report

Type of Action Drilling Operations

Date Sundry Submitted: 12/17/2020

Disposition: Accepted Disposition Date: 12/21/2020

Remarks: Test 11.75 csg to 1500 psi, 30 mins (good test) 12/5/20 Drill 8.75 inch hole to 10416 ft. on 12/8/20 12/9/20 Run 7.625 inch, 29.70#, HCL-80/RYP-110/P110 casing set at 10406 ft. 12/9/20 Cement casing with 560 sxs, 114 bbls, 1.23 yld Class H tail cmt. Bump plug. No returns Estimated TOC = 6329 ft. Perform bradenhead squeeze cement job with 800 sxs, 218 bbls, 1.53 yld Class H lead cmt. No Cement to surface. TOC = 33 ft. (Total 1360 sxs cmt).

Page 1 of 1

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 518316

#### **CONDITIONS**

Operator:	OGRID:
XTO PERMIAN OPERATING LLC.	373075
6401 HOLIDAY HILL ROAD	Action Number:
MIDLAND, TX 79707	518316
	Action Type:
	[C-103] Sub. Drilling (C-103N)

### CONDITIONS

Created By	Condition	Condition Date
crystal.walker	Report pressure test on next sundry. Include test pressure and duration.	11/3/2025