



OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

(Submit 2 copies to above address)

Property Name SCHALK 57 #002A Location: Unit C Section 12 Township 30N Range 05W
(Well Name and Number)

Pressure (Shut-in or Producing) _____ Tubing 144 Intermediate NA Casing 160 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	Ø	160	/	/			/	
10 minutes	Ø	160						
15 minutes	Ø	160						
20 minutes	Ø	160			N	A		
25 minutes	Ø	160						
30 minutes	Ø	160						
5 minute SI	Ø	160						

Steady Flow		/		
Surges				
Down to Nothing	XX			
No Flow			N	A
Gas	XX			
Gas and Water				
Water				

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate NA

REMARKS:

STOP CLOKED PLUNGER WELL. WELL WAS IN OFF CYCLE ON ARRIVAL. DURING TEST
OPENED BH - SHORT SOFT PUFF DOWN TO NOTHING IN 1 SECOND. NO H₂S DETECTED (4 GAS MONITOR).

By SCOTT RODGERS _____ Witness _____
LEASE OPERATOR _____

 (Position)

NMOCD Test Area:

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 455690

CONDITIONS

Operator: SCHALK DEVELOPMENT CO P.O. Box 25825 Albuquerque, NM 87125	OGRID: 20389
	Action Number: 455690
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	None	12/29/2025