



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 320-0243  
File Via OCD Permitting

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 5-20-25 Operator Rim Operating API #30-0 39-22790

Property Name Werner Well No. 2 Location: Unit P Section 5 Township 25N Range 7W

Well Status(Shut-In or Producing) Initial PSI: Tubing 10 Intermediate 10 Casing 10 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>10</u>		<u>10</u>		
10 min	<u>10</u>		<u>10</u>		
15 min	<u>10</u>		<u>10</u>		
20 min					
25 min					
30 min					

**FLOW CHARACTERISTICS**

BRADENHEAD      INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR  FRESH  SALTY  SULFUR  BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 10

INTERMEDIATE

REMARKS:

By Terry Werner  
Rumber  
(Position)

Witness \_\_\_\_\_

E-mail address \_\_\_\_\_

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 477784

**CONDITIONS**

Operator:  RIM OPERATING, INC. 5 Inverness Drive East Englewood, CO 80112	OGRID: 372497
	Action Number: 477784
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

**CONDITIONS**

Created By	Condition	Condition Date
jason.heslop	None	12/29/2025