



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-8-2025 Operator Rim Operating API #30-0 39-24079

Property Name COOGAR COM 4 Well No. 1A Location: Unit I Section 4 Township 25 Range 2W

Well Status(Shut-In or Producing) Initial PSI: Tubing 312 Intermediate _____ Casing 284 Bradenhead N/A

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Bradenhead	Csg	Int	Csg	Int
TIME						
5 min			<u>284</u>			
10 min						
15 min						
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	_____
Surges	_____
Down to Nothing	_____
Nothing	_____
Gas	_____
Gas & Water	_____
Water	_____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

BRADEN HEAD DOES NOT EXIST

By Tony Schmitz Witness _____

Pumper
(Position)

E-mail address tschmitz@rimop.com

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 477819

CONDITIONS

Operator: RIM OPERATING, INC. 5 Inverness Drive East Englewood, CO 80112	OGRID: 372497
	Action Number: 477819
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	This has been the same in all the other braden head reports in the well file.	12/29/2025