



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/9/2025 Operator 3000 dba Blackhawk energy corp. API #30-0 39-25130

Property Name JIC 30-03-28 Well No. 1 Location: Unit 1 Section 28 Township 30N Range 3W

Well Status(Shut-In or Producing) Initial PSI: Tubing 530 Intermediate Casing 530 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead	INTERM	Int	Csg
TIME					
5 min	0	530			
10 min	0	530			
15 min	0	530			
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

Well shot in, BH had 0-psi and a very small puff. After 5 min shut in BH had 0-psi and nothing else.

By Robert Talamante
Plant/lease Operator
(Position)

Witness

E-mail address rtalamante@blackhawkenergycorp.com

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 452823

CONDITIONS

Operator: JICARILLA ENERGY CO P.O. 1048 Farmington, NM 87401	OGRID: 11859
	Action Number: 452823
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	Accepted for record only.	12/29/2025