



# NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 320-0243  
File Via OCD Permitting

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/6/25 Operator Rim operating API #30-0 39-30122

Property Name Budgermont Well No. 2A Location: Unit P Section 14 Township 25N Range 2W

Well Status(Shut-In or Producing) Initial PSI: Tubing 150 Intermediate      Casing 250 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>0</u>		<u>250</u>		
10 min	<u>0</u>		<u>250</u>		
15 min	<u>0</u>		<u>250</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>    </u>	<u>    </u>
Surges <u>    </u>	<u>    </u>
Down to Nothing <u>    </u>	<u>    </u>
Nothing <u>    </u>	<u>    </u>
Gas <u>    </u>	<u>    </u>
Gas & Water <u>    </u>	<u>    </u>
Water <u>    </u>	<u>    </u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE     

REMARKS:

      
      
    

By Luke Post  
Operator  
(Position)

Witness     

E-mail address LPost@rimop.com

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 477964

CONDITIONS

Operator:  RIM OPERATING, INC. 5 Inverness Drive East Englewood, CO 80112	OGRID:  372497
	Action Number:  477964
	Action Type:  [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	None	12/29/2025