



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170


[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**


(submit 1 copy to above address)

Date of Test 8-4-2025 Operator Enduring Resources API #30-039-31445Property Name NE Lybrook Com Well No. 262H Location: Unit 6 Section 6 Township 23 Range 6Well Status(Shut-In or Producing) Initial PSI: Tubing 215 Intermediate N/A Casing 638 Bradenhead -3.1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH



**FLOW CHARACTERISTICS**  
**BRADENHEAD**      **INTERMEDIATE**

If bradenhead flowed water, check all of the descriptions that apply below: N/ACLEAR  FRESH  SALTY  SULFUR  BLACK **5 MINUTE SHUT-IN PRESSURE**BRADENHEAD 0INTERMEDIATE N/A

## REMARKS:

BTI was on a vacuum for 19 seconds when valve was opened- 30 day post completion ~By Danny MontoyaWitness Jason Heslop  
NM DCRHSELead  
(Position)E-mail address dmontoya@enduringresources.com

**From:** Greg Olson <[golson@enduringresources.com](mailto:golson@enduringresources.com)>  
**Sent:** Monday, May 12, 2025 5:59 AM  
**To:** Shaw-Marie Ford <[sford@enduringresources.com](mailto:sford@enduringresources.com)>; Heather Huntington <[Hhuntington@enduringresources.com](mailto:Hhuntington@enduringresources.com)>  
**Cc:** Chris Longwell <[CLongwell@enduringresources.com](mailto:CLongwell@enduringresources.com)>; Sean Owens <[SOwens@enduringresources.com](mailto:SOwens@enduringresources.com)>; Jennifer Korinek <[jkorinek@enduringresources.com](mailto:jkorinek@enduringresources.com)>; Ryan McGilvery <[rmcgilvery@enduringresources.com](mailto:rmcgilvery@enduringresources.com)>  
**Subject:** FW: NE LYBROOK COM 262H

Good Morning Shaw / Heather,

Attached are the CBL logs for the NE Lybrook Unit 262H well. Cement was not seen at surface, but the log shows good cement at 700', and weak cement into surface casing with some spotty cement so surface. Both Virgil Lucero with the BLM and Monica Kuehling with the NMOCD were verbally notified and both gave their approval to drill and complete the well. **Monica would like us to perform a braden head test approximately one month after completion.**

Shaw, Logs are attached for filing with the agencies if you would please.  
Heather, would you mind scheduling the braden head test for the NMOCD?

Greatly appreciated,

Greg Olson  
Enduring Resources  
[golson@enduringresources.com](mailto:golson@enduringresources.com)  
(303) 408-4097 cell  
(303) 350-5117 office

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 493100

**CONDITIONS**

Operator:  ENDURING RESOURCES, LLC 6300 S Syracuse Way Centennial, CO 80111	OGRID: 372286
	Action Number: 493100
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

**CONDITIONS**

Created By	Condition	Condition Date
jason.heslop	None	12/29/2025