



**NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test

4/8/25

Operator

Schalk Development

API # 30-039-23881

Property Name

SCHALK GAVILAN #001

Location: Unit B Section 34 Township 25N Range 03W

(Well Name and Number)

Pressure (Shut-in or Producing)

Tubing 185

Intermediate

N/A

Casing

210

Bradenhead

0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead		
	BH Blowdown	Casing Monitor	Intermediate Monitor
5 minutes	0	210	N/A
10 minutes	0	212	
15 minutes	0	215	
20 minutes			↓
25 minutes			↓
30 minutes			↓
5 minute SI	0	217	

Intermediate	
Intermediate Blowdown	Casing Monitor
N/A	N/A

Bradenhead Flowed	Intermediate Flowed
Steady Flow	N/A
Surges	
Down to Nothing	
No Flow	X
Gas	
Gas and Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

Bradenhead had 0 Psi.  
Well has been shut in.  
Casing pressure was 84 in 2022.

By Wyatt Templeton  
Lease Operator  
(Position)

Witness \_\_\_\_\_

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 455180

**CONDITIONS**

Operator:  SCHALK DEVELOPMENT CO P.O. Box 25825 Albuquerque, NM 87125	OGRID: 20389
	Action Number: 455180
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

**CONDITIONS**

Created By	Condition	Condition Date
jason.heslop	None	1/5/2026