



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 320-0243  
File Via OCD Permitting

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 21-MAY-2025 Operator SIMCO API #30-0 45-08335

Property Name MANSLOW GC Well No. 1 Location: Unit F Section 15 Township 29 Range 12

Well Status(Shut-In or Producing) Initial PSI: Tubing 91 Intermediate N/A Casing 91 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS		
	Bradenhead	INTERM	Bradenhead	INTERMEDIATE		
BH	Int	Csg	Int	Csg		
TIME						
5 min	0	N/A	91			
10 min	0		91			
15 min	0		91	N/A		
20 min	0		91			
25 min	0		91			
30 min	0		91			

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR  FRESH  SALTY  SULFUR  BLACK

**5 MINUTE SHUT-IN PRESSURE**

BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

BRADENHEAD PLUGGED TO nothing.

By Heather Alexander  
Field Tech  
(Position)

Witness

E-mail address

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 540536

**CONDITIONS**

Operator:  SIMCOE LLC 1199 Main Ave., Suite 101 Durango, CO 81301	OGRID: 329736
	Action Number: 540536
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

**CONDITIONS**

Created By	Condition	Condition Date
jason.heslop	None	1/6/2026