

BUCKLE
1425 N. French Dr., Hobbs, NM 88240

Office II
815 S 1st Street, Artesia, NM 88210

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Oxy USA, INC	API Number 30-025-44185
Property Name Mesa Verde BS Unit	Well No. SH

Surface Location								
UL - Lot	Section	Township	Range	Feet From	N/S Line	Feet From	E/W Line	County
	17	24S	32E	200'	S	99S	E	Lea

Well Status					DATE			
TAD Well	SHUT-IN	INJECTOR	PRODUCING					
Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	INJ	SWD	OIL <input checked="" type="checkbox"/>	GAS <input type="checkbox"/>	10-06-24

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surface	(B) Interim(1)	(C) Interim(2)	(D) Prod Cong	(E) Tubing
Pressure	0	10	N/A	796	108
Flow Characteristics	Puff Gas				
Puff	<input checked="" type="checkbox"/> Y / <input type="checkbox"/> N	<input checked="" type="checkbox"/> Y / <input type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N
Steady Flow	<input type="checkbox"/> Y / <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y / <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N
Surges	<input type="checkbox"/> Y / <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y / <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N
Down to nothing	<input type="checkbox"/> Y / <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y / <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N
Gas or Oil	<input type="checkbox"/> Y / <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y / <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N
Water	<input type="checkbox"/> Y / <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y / <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N	<input type="checkbox"/> Y / <input type="checkbox"/> N

Remarks - Please state for each string (A,V,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A) No Pressure
B) 10 psi, Bled off to zero psi

Signature:	OIL CONSERVATION DIVISION
Printed name: Moises Jaquez	Entered into RBDMS
Title: Workover and Completions Specialist	Re-test:
E-mail Address: Moises_Jaquez@oxy.com	
Date: 10-06-24	
Phone: 575 408 6637	
Witness: Fabian Hernandez (432) 888-0211	

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 441560

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 441560
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
robert.asher	None	1/26/2026