

Submit a Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-045-34433
5. Indicate Type of Lease
STATE [X] FEE []
6. State Oil & Gas Lease No.
B-10894-14

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [] Gas Well [X] Other []
2. Name of Operator
HILCORP ENERGY COMPANY
3. Address of Operator
382 Road 3100, Aztec, NM 87410
4. Well Location
Unit Letter P : 1080 feet from the S line and 850 feet from the E line
Section 16 Township 26N Range 9W NMPM San Juan County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)
6348'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON []
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING [] MULTIPLE COMPL []
DOWNHOLE COMMINGLE []
CLOSED-LOOP SYSTEM []
OTHER: MIT [X]
SUBSEQUENT REPORT OF:
REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPNS. [] P AND A []
CASING/CEMENT JOB []
OTHER: []

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Hilcorp Energy Company requests to conduct a Mechanical Integrity Test to extend the Temporary Abandon status of the subject well per the attached procedure and wellbore schematic to evaluate future potential.

Spud Date: []

Rig Release Date: []

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tammy Jones TITLE Operations/Regulatory Technician - Sr. DATE 2/16/2026

Type or print name Tammy Jones E-mail address: tajones@hilcorp.com PHONE: (505) 324-5185

For State Use Only

APPROVED BY: TITLE DATE

Conditions of Approval (if any):



HILCORP ENERGY COMPANY
Huerfano Unit Com 133E

Prepared by:	Stefan Lattimer
Preparation Date:	2/16/2026

WELL INFORMATION			
Well Name:	Huerfano Unit Com 133E	State:	NM
API #:	3004534433	County:	Rio Arriba
Area:	9	Latitude:	
Route:	907	Longitude:	
Spud Date:	January 30, 2008	Formations:	Dakota

PROJECT DESCRIPTION
Hilcorp Energy Company requests approval to perform a mechanical integrity test (MIT) on the Huerfano Unit Com 133E.

CONTACTS			
Title	Name	Office Phone #	Cell Phone #
Engineer	Stefan Lattimer		713-701-2673
Area Foreman	Clayton Hamilton		419-3455
Lead	Danny Trujillo		330-4763
Artificial Lift Tech	Daniel Rios		419-3974
Operator			

JOB PROCEDURES
1 Hold pre-job safety meeting. Verify cathodic is off. Comply with all NMOCD, BLM, and HEC safety and environmental regulations.
2 Record current wellhead pressures and enter them in Wellview. If there is pressure on the BH, contact Operations Engineer.
3 Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure (if any is present).
4 MIRU pump truck. Load the casing with 2% KCL water and corrosion inhibitor.
5 Perform Mechanical Integrity Test (MIT) by pressure testing the 4.5" casing above the bridge plug set @ 6,370' to 560 psig for 30 minutes in accordance with NMOCD standards with required witness present.
6 Notify Operations Engineer and submit test results to HEC Regulatory Technicians as quickly as possible. RDMO.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 554296

CONDITIONS

Operator: HILCORP ENERGY COMPANY 1111 Travis Street Houston, TX 77002	OGRID: 372171
	Action Number: 554296
	Action Type: [C-103] NOI Temporary Abandonment (C-103I)

CONDITIONS

Created By	Condition	Condition Date
andrew.fordyce	Passing MIT test in accordance with 19.15.26.11 or 19.15.25.12-14 NMAC will be required at time of work.	2/17/2026
andrew.fordyce	Call the OCD North Inspection team (505-320-0243) to schedule MIT / BHT.	2/17/2026