Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 May 27, 2004	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240		W	ELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION)-021-20584	· · · · · · · · · · · · · · · · · · ·
District III	1220 South St. Francis Dr.		Indicate Type of I	FEE 🛛
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 8/505		State Oil & Gas I	
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	7	Leace Name or I'	Init Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			ibby Minerals LLC	C 1931
1. Type of Well: Oil Well	Gas Well Other CO2 Well	8.	Well Number 14	-1-F
2. Name of Operator Reliant Exploration & Production, LLC.			9. OGRID Number 251905	
3. Address of Operator			10. Pool name or Wildcat	
10817 West County Road 60 Midland, TX 79707			Bravo Dome 96010	
4. Well Location				
Unit Letter F :	1700feet from theNorth	line and	1700_feet from th	e West line
Section 14	Township 19 N	Range 31 E	NMPM	County Harding
\$ 100 miles	11. Elevation (Show whether DR, 4499	RKB, RT, GR, etc.)	- 10 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	
Pit or Below-grade Tank Application 🔲	r Closure 🔲			
Pit typeDepth to Groundw	aterDistance from nearest fresh w	rater well Distance	e from nearest surface	water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Constr	uction Material	
12. Check	Appropriate Box to Indicate N	ature of Notice, Re	port or Other D	ata
	•••		•	
			QUENT REPO	JRTOF: LTERING CASING □
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLI	_	AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JO		
· OLE GIVILIZING AND ING		ONO INCOMENTO	,,,	
OTHER:		OTHER:		
	oleted operations. (Clearly state all p			
or recompletion.	ork). SEE RULE 1103. For Multiple	le Completions: Attact	i wellbore diagram	of proposed completion
or recompletion.				
				•
See Attachment				
•				
				•
I hereby certify that the information	above is true and complete to the be	est of my knowledge an	id belief. I further c	
grade tank has been/will be constructed or			n (attached) alternativ	
	closed according to NMOCD guidelines D	I, a general permit □ or a Nanae	I	ve OCD-approved plan □. OATE 9-30-13
grade tank has been/will be constructed or SIGNATURE	closed according to NMOCD guidelines D	I, a general permit □ or a Nanae	I	ve OCD-approved plan □. OATE 9-30-13
grade tank has been/will be constructed or	closed according to NMOCD guidelines D	I, a general permit □ or a Nanae	I	ve OCD-approved plan .

Libby Minerals LLC 1931 14-1-F

9/20/13

(06:00) MIRU Reliant Rig #1. KB = 10' AGL.

9/21/13

Finish RU. Inspected rig, drill collars, and drill pipe.

Spud in at (07:00) / Drill 12.25" surface hole from 0' to 724' / Average WOB 7 / 95-100 RTS / 390 gpm @ 1000 psi.

(20:15) Circulate and condition hole.

(21:45) TOOH

9/22/13

(00:30)Dropped 60 inch pipe wrench in hole breaking bit. Wait on fishing equipment.

(06:00) TIH with 11" magnet to get fish. Started pushing fish at 535'. Rotated and circulate. TOOH. No fish.

(14:00) TIH to fish to 550'.

(16:00) TOOH. No fish.

(18:30) TIH. Pushed fish to 722'. Worked. TOOH. Retrieved 12" piece of wrench handle.

TIH. Worked fish with saw tooth. TOOH. No Fish. TIH. Worked fish with texas tooth. TOOH. Retrieved 4 inch piece of handle.

9/23/13

TIH with saw tooth. Work fish. TOOH.

9/24/13

Fish. Got all pieces of 60 back but top jaw. RIH and Mill top jaw. RIH with magnet.

9/25/13

Drill 12.25" surface hole from 724' to 752' / Average WOB 10 / 95-100 RTS / 390 gpm @ 1000 psi.

(17:00)Ran 8.625, 24.0 lb/ft, J-55, ST&C, from 10' to 752'.

(20:30)Circulate

(21:00) MIRU O-Tex to pump surface cement job as follows:

Pressure tested lines to 2000 psi. Pumped 10 bbl spacer. Pumped 650 sks of Class C + 2% Calcium chloride cement at 14.8 ppg at 4 BPM and 150 psi. Dropped top plug and pumped 45 bbls displacement at 3 BPM and 200 psi. Bumped plug to 1000 psi. Float held. Circulated a total of 25 bbls to surface. Plug down at 23:00 hours on 9/25/2013. WOC

9/26/13

(03:00) Remove landing joint and nipple up BOP

(05:00)TIH

(06:45) Drilled 7 7/8 production hole from 752' to 1830' / Average WOB 10 / 95 RTS / 380 gpm @ 750 psi.

9/27/13

Drill 7 7/8 production hole from 1830' to 2345' / Average WOB 13 / 98 RTS / 380 gpm @ 950 psi

(11:30) Circulate.

(14:00) TOOH

(21:30)MIRU Weatherford wire line to run open hole logs.

9/28/13

(03:00)Ran 5 ½ casing as follows: 5.5", 15.5#, J-55, 8 RD, casing from 8' to 2277'.

(07:00) Circulate and Condition hole

(11:30)MIRU O-Tex to pump cement as follows:

Pressure tested lines to 2500 psi. Pump 10 bbls spacer. Pumped 180 sks lead cement Class C + 2% GYP + 3%Calcl2 + 2% SM + 1/8 lb per sk celloflake at 11.1 ppg at 4 bpm at 80 psi. Pumped 160 sks tail cement Class C + 2% GYP + 3%Calcl2 + 2% SM + 1/8 lb per sk celloflake at 13.2 ppg at 4 bpm at 20 psi. Dropped top plug. Displaced cement with 53 bbls water at 3 bpm and 600 psi. Bumped plug at 1110 psi.. Float equipment held. Circulated 56 bbls to surface. Plug down at 13:00 hours on 9/28/13. Nipple down BOP equipment and clean pits and location.

(17:00) Nipple down BOP equipment and clean pits and location.

Rig released at 17:00 hours on 9/28/13.

RECEIVED OCD

2013 OCT -3 P 1:40



September 30, 2013

Mr. Ed Martin District IV Supervisor New Mexico Oil Conservation Division 1220 South St. Francis Santa Fe, NM 87505

Re: Form C-103

Dear Mr. Martin:

Please find enclosed for your approval the sundry notice for the following well;

Libby Minerals LLC 1931 14-1-F.

Please send the approved notice to my attention at the following address;

7714 Georgetown Drive

Amarillo, TX 79119

Please let me know if you have any questions.

Sincerely,

Vance Vanderburg vance@reliantholdingsltd.com

432-559-7085