Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 May 27, 2004	
District I 1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION		30-021-20565	
District III	1220 South St. Francis Dr.		<ol> <li>Indicate Type of Lease</li> <li>STATE ☐ FEI</li> </ol>	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Conto Lo NIM 075/15		6. State Oil & Gas Lease No	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agre	ement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				
			Libby Minerals LLC 1931 8. Well Number 16-2-N	
1. Type of Well: Oil Well Gas Well Other CO2 Well				
2. Name of Operator			9. OGRID Number	:
Reliant Exploration & Production, LLC.  3. Address of Operator			251905 10. Pool name or Wildcat	
10817 West County Road 60 Midland, TX 79707			Bravo Dome 96010	
4. Well Location				
Unit LetterN:	660feet from theSouth	line and21	190_feet from theWes	stline
Section 16	Township 19 N	Range 31 E		ty Harding
	11. Elevation (Show whether DR,	RKB, RT, GR, etc.)		
Pit or Below-grade Tank Application 🔲 o	4421		in the second se	
Pit type Depth to Groundw	<del></del>	atan wall Distan	noo faara maanaat amafaan matan	
Pit Liner Thickness: mil			nce from nearest surface water struction Material	
	Below-Grade Tank: Volume			
12. Check A	Appropriate Box to Indicate Na	ature of Notice, R	leport or Other Data	
NOTICE OF IN	ITENTION TO:	SUBS	<b>EQUENT REPORT O</b>	F:
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲	REMEDIAL WORK		CASING 🗌
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRIL	<u> </u>	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB 🗌	
OTHER:	п	OTHER:		П
13. Describe proposed or comp	oleted operations. (Clearly state all p		give pertinent dates, including	g estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.				
11/13/13	70.1.1			
1931 # 16-2-N R/U Kill trk. Pump 70 bbls water down 5 1/2" csg and kill well. R/U and pickup 62 jts 2 7/8" 6.5# coated j-55 8				
rd total 2007.56' set in full string weight. Made 4 swab runs from 1950'. Found fluid at 1400' the first 3 runs, last run found fluid at 900' spotted. Recovered 12 bbls +/- water. SION.				
11/14/13			•	•
RDMO				
	•			
			•	
I hereby certify that the information	above is true and complete to the be	est of my knowledge	and belief. I further certify that	any pit or below-
grade tank has been/will be constructed or	closed according to NMOCD guidelines	🕽, a general permit 🗌 oi	r an (attached) alternative OCD-ap	proved plan 🗌.
SIGNATURE	TITLE	Maria	ከልጥሮ	11-18-13
J. J	111111111111111111111111111111111111111	10 angjer	DATE	· · · · · · · · · · · · · · · · · · ·
Type or print name	lands by E-mail ad	dress: Varirere	Huts uses non Telephone No	). 432-555-7085
For State Use Only	1 1			•
APPROVED BY:	VIA TITLE	DISTRICT S	UPERVISOR DATE /	1/0//0010