

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2103643602
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Harvest Midstream Company	OGRID 373888
Contact Name Monica Smith	Contact Telephone 505-632-4625
Contact email msmith@harvestmidstream.com	Incident # (assigned by OCD) nAPP2103643602
Contact mailing address 1755 Arroyo Dr., Bloomfield, NM 87413	

Location of Release Source

Latitude 36.50544 Longitude -107.12019
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Trunk E Facility	Site Type Compressor Station
Date Release Discovered 12/9/2020 - 1 pm	API# (if applicable)

Unit Letter	Section	Township	Range	County
D	11	26N	3W	Rio Arriba

Surface Owner: ☐ State ☐ Federal ☒ Tribal ☐ Private (Name):
Jicarilla

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) about 30	Volume Recovered (bbls) about 30
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
<input checked="" type="checkbox"/> Condensate	Volume Released (bbls) about 92	Volume Recovered (bbls) about 92
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

A gasket failed on one of the valves allowing the 122 bbls of liquid to leak into the containment. The leak has been repaired.

Form C-141

Page 2


State of New Mexico
Oil Conservation Division

Incident ID	nAPP2103643602
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? NMAC 19.15.29.7(A1): an unauthorized release of liquids exceeding 25 bbls
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Notice provided via electronic mail by Kijun Hong to Cory Smith and Jim Griswold of NMOCDD on Dec. 10, 2020 10:33 AM	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.
If all the actions described above have <u>not</u> been undertaken, explain why:
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
Printed Name: <u>Kijun Hong</u> Title: <u>Environmental Specialist</u> Signature:  Date: <u>2/8/2021</u> email: <u>khong@harvestmidstream.com</u> Telephone: <u>505-632-4475</u>
<u>OCD Only</u> Received by: _____ Date: _____

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 17282

CONDITIONS OF APPROVAL

Operator: HARVEST FOUR CORNERS, LLC 1111 Travis Street Houston, TX77002			OGRID: 373888	Action Number: 17282	Action Type: C-141
OCD Reviewer	Condition				
marcus	When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-141.				