

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAPP2109836159
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party ETP Crude LLC	OGRID
Contact Name Lyanne Lara	Contact Telephone 432-425-5710
Contact email Lyanne.lara@energytransfer.com	Incident # (assigned by OCD) nAPP2109836159
Contact mailing address 600 N. Marienfeld St. Suite 700 Midland, TX 79701	

Location of Release Source

Latitude 32.268691 Longitude -103.618306
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Shurvesa System Triste Draw 6" Lateral	Site Type Pipeline
Date Release Discovered 3/2/2021	API# (if applicable)

Unit Letter	Section	Township	Range	County
L	S30	T23S	R33E	Lea

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: Hughes Properties, LLC)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 37.1	Volume Recovered (bbls) 0
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release


The release was attributed to the corrosion of the pipeline segment. Based on volumetric measurements and dimensions of spill area/impacted soil, approximately 37.1 bbls of crude oil was released.

Incident ID	NAPP2109836159
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? An unauthorized release of a volume of 25 barrels or more.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Given by Lyanne Lara via email to NMOCD District 1 on 3/3/2021 at 1:50pm CST.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped.	
<input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment.	
<input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.	
<input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Lyanne Lara</u> Title: <u>Environmental Specialist</u>	
Signature:  Date: <u>04/08/2021</u>	
email: <u>lyanne.lara@energytransfer.com</u> Telephone: <u>432-425-5710</u>	
<u>OCD Only</u>	
Received by: <u>Ramona Marcus</u> Date: <u>4/30/2021</u>	

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 23427

CONDITIONS OF APPROVAL

Operator:	ETC TEXAS PIPELINE, LTD.	8111 Westchester Drive	OGRID:	371183	Action Number:	23427	Action Type:	C-141
	Suite 600	Dallas, TX75225						

OCD Reviewer	Condition
rmarcus	The submitted C-141 is accepted with the following condition(s): The lateral and longitudinal information does not match the ULSTR regarding the release location. Please correct the conflicting information and report back to OCD. The information is landing on ULSR: M-30-23S-33E. When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-141.