



Certificate of Analysis

Number: 6030-21080194-010A

Artesia Laboratory

200 E Main St.
Artesia, NM 88210
Phone 575-746-3481Alex Batista
Taprock
602 Park Point Drive
Ste. 200
Golden, CO 80401

Aug. 25, 2021

Station Name: Yada Fed Com 135
Station Number: 7060303
Sample Point: Meter run
Formation: Spot
County: Lea
Type of Sample: Spot-Cylinder
Heat Trace Used: N/A
Sampling Method: Fill and Purge
Sampling Company: SPLSampled By: James Hill
Sample Of: Gas Spot
Sample Date: 08/17/2021 10:45
Sample Conditions: 139.8 psig, @ 128.6 °F Ambient: 90 °F
Effective Date: 08/17/2021 10:45
Method: GPA-2261M
Cylinder No: 5030-02476
Instrument: 70104124 (Inficon GC-MicroFusion)
Last Inst. Cal.: 07/08/2021 0:00 AM
Analyzed: 08/24/2021 09:52:07 by KNF

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.73 psia
Hydrogen Sulfide	NIL	0.20000	0.290	
Nitrogen	1.282	1.29614	1.546	
Carbon Dioxide	1.424	1.43976	2.698	
Methane	71.822	72.64287	49.632	
Ethane	11.270	11.39915	14.597	3.062
Propane	6.652	6.72799	12.635	1.862
Iso-Butane	1.011	1.02245	2.531	0.336
n-Butane	2.447	2.47455	6.125	0.783
Iso-Pentane	0.763	0.77151	2.371	0.283
n-Pentane	0.705	0.71326	2.192	0.260
Hexanes	0.612	0.61889	2.271	0.256
Heptanes	0.468	0.47294	2.018	0.219
Octanes	0.182	0.18448	0.897	0.095
Nonanes Plus	0.036	0.03601	0.197	0.020
	98.674	100.00000	100.000	7.176

Calculated Physical Properties	Total	C9+
Calculated Molecular Weight	23.48	128.26
Compressibility Factor	0.9955	
Relative Density Real Gas	0.8141	4.4283

GPA 2172 Calculation:

Calculated Gross BTU per ft³ @ 14.73 psia & 60°F

Real Gas Dry BTU	1358.2	7012.5
Water Sat. Gas Base BTU	1335.1	6890.4
Ideal, Gross HV - Dry at 14.73 psia	1352.0	7012.5
Ideal, Gross HV - Wet	1328.5	6890.4

Comments: H2S Field Content 2000 ppm
CO2 1.3%
Mcf/dady 2179.5

Data reviewed by: Eric Ramirez, Analyst

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.

Flaring Summary

battery	9/24/2021
Yada CTB B	151.00
Grand total	151.00

date

Data table:
flare_report_data (2)
Colors:
All values

battery

Sum(TOTAL FLARE (HP + LP))

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 52075

QUESTIONS

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043
	Action Number: 52075
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS**Prerequisites**

Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.

Incident Well	Not answered.
Incident Facility	[fAPP2126033332] Yada CTB B

Determination of Reporting Requirements

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting and/or flaring caused by an emergency or malfunction	Yes
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a venting and/or flaring event	Yes, minor venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved

Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	72
Nitrogen (N2) percentage, if greater than one percent	1
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	1
Oxygen (O2) percentage, if greater than one percent	0

If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.

Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting and/or flaring was discovered or commenced	09/23/2021
Time venting and/or flaring was discovered or commenced	06:00 AM
Time venting and/or flaring was terminated	06:00 PM
Cumulative hours during this event	2

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
----------------------------------	---------------

Natural Gas Flared (Mcf) Details	Cause: High Line Pressure Gas Compressor Station Natural Gas Flared Released: 151 Mcf Recovered: 0 Mcf Lost: 151 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity

Was or is this venting and/or flaring a result of downstream activity	Not answered.
Was notification of downstream activity received by you or your operator	Not answered.
Downstream OGRID that should have notified you or your operator	Not answered.
Date notified of downstream activity requiring this venting and/or flaring	Not answered.
Time notified of downstream activity requiring this venting and/or flaring	Not answered.

Steps and Actions to Prevent Waste

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	Lucid Energy, our midstream provider, saw their compressor go down on the sour line. Both sour and sweet lines were shut in to clean filters and due to this Tap Rock flare numbers spiked larger than regulated volumes. Once Lucid can solve their issue, Tap Rock should see normal operations. No timetable has been given to fix this issue.
Steps taken to limit the duration and magnitude of venting and/or flaring	N/A as this is a midstream problem
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	N/A as this is a midstream problem

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 52075

CONDITIONS

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043
	Action Number: 52075
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
bramsey	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	9/27/2021