



Certificate of Analysis

Number: 6030-21060083-004A

Artesia Laboratory

200 E Main St.

Artesia, NM 88210

Phone 575-746-3481

Jerry Mathews
 Spur Energy
 1012 Marquez Place, Suite 106b
 Santa Fe, NM 87505

June 09, 2021

Station Name: Dorami CTB
 Station Number: N/A
 Station Location: Spur
 Sample Point: Meter run
 Type of Sample: Spot-Cylinder
 Heat Trace Used: N/A
 Sampling Method: Fill and Purge
 Sampling Company: SPL
 Analyzed: 06/08/2021 13:05:55 by KNF

Sampled By: Donavan Miller
 Sample Of: Gas Spot
 Sample Date: 06/07/2021 09:33
 Sample Conditions: 46.8 psig, @ 109 °F Ambient: 81 °F
 Effective Date: 06/07/2021 09:33
 Method: GPA-2261M
 Cylinder No: 1111-002600
 Instrument: 70104124 (Inficon GC-MicroFusion)
 Last Inst. Cal.: 05/18/2021 0:00 AM

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.73 psia
Nitrogen	2.296	2.71551	3.188	
Carbon Dioxide	1.833	2.16808	3.998	
Methane	60.705	71.78982	48.261	
Ethane	10.663	12.60992	15.889	3.387
Propane	3.052	3.60920	6.669	0.999
Iso-Butane	0.889	1.05169	2.562	0.346
n-Butane	2.109	2.49353	6.073	0.790
Iso-Pentane	0.686	0.81103	2.452	0.298
n-Pentane	0.632	0.74753	2.260	0.272
Hexanes	0.518	0.61200	2.210	0.253
Heptanes	0.581	0.68745	2.887	0.319
Octanes	0.338	0.39913	1.911	0.205
Nonanes Plus	0.258	0.30511	1.640	0.172
	84.560	100.00000	100.000	7.041

Calculated Physical Properties

	Total	C9+
Calculated Molecular Weight	23.86	128.26
Compressibility Factor	0.9954	
Relative Density Real Gas	0.8274	4.4283

GPA 2172 Calculation:

Calculated Gross BTU per ft³ @ 14.73 psia & 60°F

Real Gas Dry BTU	1339.5	7012.5
Water Sat. Gas Base BTU	1316.7	6890.4
Ideal, Gross HV - Dry at 14.73 psia	1333.3	7012.5
Ideal, Gross HV - Wet	1310.1	6890.4

Report generated by: Krystle Fitzwater

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.

Name of well or facility	Lat	Long	Daily Volume of Flared Natural Gas (MCF/D)	Commencement	Duration	Proposed Remedy
SHELBY 23 TANK BATTERY	32.636495	-104.449015	1199 MCF/D	10/6/2021	Continuous	ACO Requested
OSAGE BOYD 15 FED 09.12.13.14 TANK BATTERY	32.652839	-104.478905	1267 MCF/D	10/6/2021	Continuous	ACO Requested
LAKEWOOD FEDERAL COM NORTH BATTERY	32.625808	-104.469155	2391 MCF/D	10/6/2021	Continuous	ACO Requested
LAKEWOOD FEDERAL COM SOUTH BATTERY	32.608649	-104.479201	1575 MCF/D	10/6/2021	Continuous	ACO Requested
DORAMI 33 FEDERAL COM 2H.4H.9H TANK BATTERY	32.614416	-104.478493	899 MCF/D	10/6/2021	Continuous	ACO Requested
HUBER 10, 11, 12 FEDERAL OIL TANK BATTERY	32.610648	-104.472851	737 MCF/D	10/6/2021	Continuous	ACO Requested
SHORTY 2 STATE COM TANK BATTERY	32.8653287	-103.9504986	1119 MCF/D	10/6/2021	Continuous	Gas Rerouted
MORRIS BOYD TANK BATTERY	32.64057	-104.45889	1044 MCF/D	10/6/2021	Continuous	Gas Rerouted
GOODMAN 22 TANK BATTERY	32.64524	-104.47354	1418 MCF/D	10/6/2021	Continuous	Gas Rerouted
B&B ROSS RANCH OIL TANK BATTERY	32.648341	-104.479356	454 MCF/D	10/6/2021	Continuous	Gas Rerouted
BC FEDERAL LEASE TANK BATTERY	32.82641	-103.79216	211 MCF/D	10/6/2021	Continuous	Gas Rerouted
SHELBY 23 #1 WELL	32.6511192	-104.4537735	56 MCF/D	10/6/2021	Continuous	Gas Rerouted

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 54897

QUESTIONS

Operator: Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID: 328947
	Action Number: 54897
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS**Prerequisites**

Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.

Incident Well	Not answered.
Incident Facility	[fAPP2122833451] Dorami 33 Federal Com 2H.4H.9H Tank Battery

Determination of Reporting Requirements

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting and/or flaring caused by an emergency or malfunction	No
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a venting and/or flaring event	Yes, major venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved

Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	72
Nitrogen (N2) percentage, if greater than one percent	3
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	2
Oxygen (O2) percentage, if greater than one percent	0

If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.

Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting and/or flaring was discovered or commenced	10/06/2021
Time venting and/or flaring was discovered or commenced	12:00 AM
Time venting and/or flaring was terminated	12:00 AM
Cumulative hours during this event	24

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
----------------------------------	---------------

Natural Gas Flared (Mcf) Details	Cause: Pipeline Quality Specifications Other (Specify) Natural Gas Flared Released: 899 Mcf Recovered: 0 Mcf Lost: 899 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	flare stack
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity

Was or is this venting and/or flaring a result of downstream activity	Not answered.
Was notification of downstream activity received by you or your operator	Not answered.
Downstream OGRID that should have notified you or your operator	Not answered.
Date notified of downstream activity requiring this venting and/or flaring	Not answered.
Time notified of downstream activity requiring this venting and/or flaring	Not answered.

Steps and Actions to Prevent Waste

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	3rd party take away refusal due to capacity restraints.
Steps taken to limit the duration and magnitude of venting and/or flaring	Executed contract with midstream company to gather gas by 12/1/2021.
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	Executed contract with midstream company to gather gas by 12/1/2021.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 54897

CONDITIONS

Operator: Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID: 328947
	Action Number: 54897
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
schapman01	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	10/8/2021