

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

| | |
|----------------|----------------|
| Incident ID | nAPP2203171755 |
| District RP | |
| Facility ID | |
| Application ID | |

Release Notification

Responsible Party

| | |
|--|---|
| Responsible Party- LOGOS Operating, LLC | OGRID 289408 |
| Contact Name Jay McWilliams | Contact Telephone 1-832-794-1355 |
| Contact email jmcwilliams@logoresourcesllc.com | Incident # (assigned by OCD) nAPP2203171755 |
| Contact mailing address 2010 Afton Place Farmington, NM 87401 | |

Location of Release Source

Latitude 36.237905, _____ Longitude -107.607349 _____
(NAD 83 in decimal degrees to 5 decimal places)

| | |
|------------------------------------|---|
| Site Name- Federal Well Pad | Site Type- Well Pad |
| Date Release Discovered- 1/31/2022 | API# (if applicable)- 3003931366, 3003931367, 3003931368 Associated Wells |

| Unit Letter | Section | Township | Range | County |
|-------------|---------|----------|-------|------------|
| P | 7 | 23N | 07W | Rio Arriba |

Surface Owner: State Federal Tribal Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

| | | |
|--|--|--|
| <input type="checkbox"/> Crude Oil | Volume Released (bbls) | Volume Recovered (bbls) |
| <input type="checkbox"/> Produced Water | Volume Released (bbls) | Volume Recovered (bbls) |
| | Is the concentration of dissolved chloride in the produced water >10,000 mg/l? | <input type="checkbox"/> Yes <input type="checkbox"/> No |
| <input type="checkbox"/> Condensate | Volume Released (bbls) | Volume Recovered (bbls) |
| <input type="checkbox"/> Natural Gas | Volume Released (Mcf) | Volume Recovered (Mcf) |
| <input checked="" type="checkbox"/> Other (describe) | Volume/Weight Released (provide units) Fire no release occurred flash fire | Volume/Weight Recovered (provide units) Fire |

Cause of Release

Logos Operating, LLC. experienced a flash fire on January 31, 2022, on the Federal Pad that is located in Section 7, TWN 23N R07W in Rio Arriba County NM. (Lat/Long 36.237905, -107.607349). The employee was performing routine operations when the flash fire occurred. No liquids were released, nor did the fire cause any environmental concerns. The employee was injured and transferred to SJRMC for evaluation, investigation is pending.

| | |
|----------------|----------------|
| Incident ID | nAPP2203171755 |
| District RP | |
| Facility ID | |
| Application ID | |

| | |
|--|---|
| Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | If YES, for what reason(s) does the responsible party consider this a major release? The responsible party considers this a major release due to NMAC 19.15.29.7(A) 2a. where an unauthorized release of a volume resulted in a fire. No liquids released. |
| If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Yes, Cory Smith NMOCD District III Adriane Sandoval email attached | |

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

| |
|--|
| <input checked="" type="checkbox"/> The source of the release has been stopped. N/A <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. N/A <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. N/A <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately. N/A |
| If all the actions described above have <u>not</u> been undertaken, explain why: |
| Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation. |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. |
| Printed Name: <u>Vanessa Fields</u> Title: <u>Agent/ SHE Permitting Manager</u> Signature:  Date: <u>2/14/2022</u> email: <u>vanessa@walsheng.net</u> Telephone: <u>505-787-9100</u> |
| <u>OCD Only</u> Received by: <u>Ramona Marcus</u> Date: <u>02/15/2022</u> |

| | |
|----------------|----------------|
| Incident ID | nAPP2203171755 |
| District RP | |
| Facility ID | |
| Application ID | |

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

- A scaled site and sampling diagram as described in 19.15.29.11 NMAC **N/A**
- Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection) **N/A**
- Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling) **N/A**
- Description of remediation activities **N/A**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Vanessa Fields Title: Agent/ SHE Permitting Manager

Signature:  Date: 2/14/2022

email: vanessa@walsheng.net Telephone: 505-787-9100

OCD Only

Received by: Ramona Marcus Date: 2/15/2022

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: Nelson Velez Date: 03/09/2022

Printed Name: Nelson Velez Title: Environmental Specialist – Adv

NAPP2203171755

Vanessa Fields

From: Vanessa Fields
Sent: Monday, January 31, 2022 8:10 PM
To: Adrienne.Sandoval@state.nm.us; Smith, Cory, EMNRD; Nelson.Velez@state.nm.us; Adeloye, Abiodun
Cc: Krista McWilliams; Kelly Maxwell; Marcia Brueggenjohann; 'Robert Bixler'; 'Samantha Gomez'
Subject: Logos Operating, LLC. Flash Fire Federal Pad Section 7, TWN 23N R07W in Rio Arriba County NM. Lat/Long 36.237905,-107.607349 INC# nAPP2203171755

Good Evening,

Logos Operating, LLC. experienced a flash fire on January 31, 2022 at 9:00am on the Federal Pad that is located in Section 7, TWN 23N R07W in Rio Arriba County NM. (Lat/Long 36.237905,-107.607349). The employee was performing routine operations when the flash fire occurred . No liquids were released, nor did the fire cause any environmental concerns. The employee was injured and transferred to SJRMC for evaluation, investigation is pending.

Vanessa Fields

Environmental /Regulatory Compliance Manager

Walsh Engineering

O: 505-327-4892

C: 505-787-9100

vanessa@walsheng.net



www.walsheng.net

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS
 Action 81299

CONDITIONS

| | |
|---|---|
| Operator: LOGOS OPERATING, LLC 2010 Afton Place Farmington, NM 87401 | OGRID: 289408 |
| | Action Number: 81299 |
| | Action Type: [C-141] Release Corrective Action (C-141) |

CONDITIONS

| Created By | Condition | Condition Date |
|------------|-----------|----------------|
| nvelez | None | 3/9/2022 |