

Closure Report

nAPP2132155516

Site Description

Site Name:	GOODNIGHT 26 FEDERAL #1 BATT
Company:	Oxy
Legal Description:	U/L I, Section 26, T23S, R29E
County:	Eddy County, NM
GPS Coordinates:	N 32.27325 W -103.94743

Release Data

Date of Release:	7/31/2019
Type of Release:	Produced water & Crude Oil
Source of Release:	PUMP FAILURE
Volume of Release:	CRUDE OIL 4 bbls PRODUCED WATER 6bbls
Volume Recovered:	CRUDE OIL 0 bbls PRODUCED WATER 0bbls

Remediation Specifications

Remediation Parameters:	Removed impacted gravel from inside the liner and replaced with new gravel
Remediation Activities:	AUGUST 12-19,2019

Supporting Documentation

Initial C-141	signed and included	
C-141, page 6	signed and included	
Pictures	Initial visit & Remedation	

Request for Closure

Based on the completion of the remediation plan as agreed upon, BBC International requests closure approval from NMOCD.

Cliff Brunson, President of BBC International Inc.

3/11/2022

Form C-141
Page 6

State of New Mexico
Oil Conservation Division

Incident ID	nAPP2132155516
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

- A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Wade Dittrich Title: Environmental Coordinator
 Signature: *Wade Dittrich* Date: 3-9-22
 email: wade_dittrich@oxy.com Telephone: (575) 390-2828

OCD Only

Received by: _____ Date: _____

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: *Jennifer Nobui* Date: 03/22/2022
 Printed Name: Jennifer Nobui Title: Environmental Specialist A

PO Box 805
Hobbs, NM 88241
575-397-6388

Liner Inspection Report

Operator: OXY

Site Name: GOODNIGHT 26 FEDERAL #1 BATT

Leak Date: 7/31/2019

Inspection Date: 2/24/2022

Inspection Results: 7/23/2021

Liner Integrity: Good Bad

Debris Removal: Yes No

Remediation Activities:

Gravel Removal: Yes No

Power Wash: Yes No

Closure Photos:

Inspected By: Rojelio Limas

Date: 2/24/2022

From: [Cliff Brunson](#)
To: "Enviro, OCD, EMNRD"
Cc: "Wade Dittrich"; "Ken Swinney"; "Jennifer Gilkey"; "Julia French"
Subject: FW: OXY - Goodnight 26 Federal #1 Battery - Liner Integrity Inspection
Date: Thursday, February 24, 2022 10:37:22 AM
Attachments: [image001.jpg](#)

There was an error on the date on the email below. It should be:

This is a notification that the liner at the Oxy Goodnight 26 Federal #1 Battery (7-31-19) (**Incident #nAPP2132155516**) is ready for inspection on Thursday, February 24, 2022 at 8:00 a.m. The liner has been cleaned and inspected for integrity.

Cliff P. Brunson, CEI, CRS
 President
 BBC International, Inc.
 World-Wide Environmental Specialists
 Mailing Address:
 P. O. Box 805
 Hobbs, NM 88241-0805 USA
 Shipping Address:
 1324 W. Marland St.
 Hobbs, NM 88240 USA
 Phone: (575) 397-6388
 Fax: (575) 397-0397
 E-Mail: cbrunson@bbcinternational.com



Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.

From: Cliff Brunson <cbrunson@bbcinternational.com>
Sent: Wednesday, February 23, 2022 5:01 PM
To: 'Enviro, OCD, EMNRD' <OCD.Enviro@state.nm.us>
Cc: 'Wade Dittrich' <Wade_Dittrich@oxy.com>; 'Ken Swinney' <kswinney@bbcinternational.com>; 'Jennifer Gilkey' <jgilkey@bbcinternational.com>; 'Julia French' <julia@bbcinternational.com>
Subject: OXY - Goodnight 26 Federal #1 Battery - Liner Integrity Inspection

This is a notification that the liner at the Oxy Goodnight 26 Federal #1 Battery (7-31-19) (**Incident #nAPP2132155516**) is ready for inspection on Tuesday, August 24, 2021 at 8:00 a.m. The liner has been cleaned and inspected for integrity.

Cliff P. Brunson, CEI, CRS
 President

BBC International, Inc.
World-Wide Environmental Specialists
Mailing Address:
P. O. Box 805
Hobbs, NM 88241-0805 USA
Shipping Address:
1324 W. Marland St.
Hobbs, NM 88240 USA
Phone: (575) 397-6388
Fax: (575) 397-0397
E-Mail: cbrunson@bbcinternational.com



Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.



GOODNIGHT 26 FEDERAL #1 BATT
7/31/2019





GOODNIGHT 26 FEDERAL #1 BATT
7/31/2019





GOODNIGHT 26 FEDERAL #1 BATT
7/31/2019





GOODNIGHT 26 FEDERAL #1 BATT
7/31/2019



District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS
 Action 89844

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 89844
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
jnobui	Closure Report Approved. Liner inspection needs to be conducted soon after incident/release.	3/22/2022