

**Closure Report****Napp2116654064****Site Description**

Site Name:	AMOCO CTB
Company:	OXY
Legal Description:	U/L: A, SECTION 21, T19S, R32E
County:	LEA COUNTY, NM
GPS Coordinates:	N32.65125 W103.76386

**Release Data**

Date of Release:	5/26/2021
Type of Release:	CRUDE OIL
Source of Release:	INTERNAL CORROSION
Volume of Release:	300 BBLS CRUDE OIL/ 0 BBLS PRODUCED WATER
Volume Recovered:	280 BBLS CRUDE OIL/ 0 BBLS PRODUCED WATER

**Remediation Specifications**

Remediation Parameters	REMOVE GRAVEL AND PRESSURE WASH LINER WHIT VACCUM TRUCK
Remediation Activities:	6/3/21, 8/31/21, 9/2/21 & 9/8/21

Plan Sent to OCD:	FROM CLIFF TO BLM NM AND WADE
OCD Approval of Plan:	
Plan Sent to BLM:	FROM CLIFF TO SPILL@BLM AND WADE
BLM Approval of Plan:	

**Supporting Documentation**

C 141 PAGE 6	SIGNED	
PICTURES	CLOSURE PICTURES	
GOOGLE EARTH MAP OF LEAK AREA		
LINER REPORT		

**Request for Closure**

Based on the completion of the remediation plan as agreed upon, BBC International requests closure approval from NMOCD.

Cliff Brunson, President of BBC International Inc.

3/10/22

Form C-141

Page 6

State of New Mexico  
Oil Conservation Division

Incident ID	nAPP2116654064
District RP	
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

**Closure Report Attachment Checklist:** *Each of the following items must be included in the closure report.*

- ☒ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☒ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☒ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☒ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Wade Dittrich Title: Environmental CoordinatorSignature:  Date: 3-9-22email: wade\_dittrich@oxy.com Telephone: (575) 390-2828**OCD Only**Received by: Chad Hensley Date: 04/05/2022

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by:  Date: 04/05/2022Printed Name: Chad Hensley Title: Environmental Specialist Advanced

# Liner Inspection Report

Operator: OXY

Site Name: AMOCO CTB

Leak Date: 5/26/2021

Inspection Date: 2/23/2022

## Inspection Results:

Liner Intergity:    Good ☒    Bad ☐

Debris Removal:    Yes ☐    No ☒

## Remediation Activities:

Gravel Removal:    Yes ☒    No ☐

Power Wash:    Yes ☒    No ☐

Closure Photos: ☒

Inspected By: KELLY

Date: 2/23/2022

**julia@bbcinternational.com**

---

**From:** Cliff Brunson <cbrunson@bbcinternational.com>  
**Sent:** Wednesday, February 23, 2022 5:01 PM  
**To:** 'Enviro, OCD, EMNRD'  
**Cc:** 'Wade Dittrich'; 'Ken Swinney'; 'Jennifer Gilkey'; 'Julia French'  
**Subject:** OXY - Amoco CTB - Liner Integrity Inspection

This is a notification that the liner at the Oxy Amoco CTB (5-26-21) (**Incident #nAPP2116654064**) is ready for inspection on Thursday, February 24 at 8:00 a.m. The liner has been cleaned and inspected for integrity.

Cliff P. Brunson, CEI, CRS  
President  
BBC International, Inc.  
World-Wide Environmental Specialists  
Mailing Address:  
P. O. Box 805  
Hobbs, NM 88241-0805 USA  
Shipping Address:  
1324 W. Marland St.  
Hobbs, NM 88240 USA  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
E-Mail: [cbrunson@bbcinternational.com](mailto:cbrunson@bbcinternational.com)




\*\*\*\*\*  
Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.  
\*\*\*\*\*




# Oxy- Amoco CTB

Leak Date: 5-26-21  
Lea County, NM  
API: 30-025-40753

## Legend

 Leak Area



Google Earth





AMOCO CTB

5/26/21



AMOCO CTB

5/26/21





AMOCO CTB

5/26/21





AMOCO CTB

5/26/21



AMOCO CTB

5/26/21





AMOCO CTB

5/26/21





**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS  
  
Action 89842

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 89842
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
chensley	Closure approved.	4/5/2022