

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-31052

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Clayton Williams Energy, Inc.	Contact <input type="checkbox"/> Matt Swierc, Production Supt.
Address Six Desta Drive, #3000, Midland, TX 79705	Telephone No. <input type="checkbox"/> (432) 682-6324
Facility Name STATE 20B #7	Facility Type <input type="checkbox"/> pumping oil well

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	Lease No. <input type="checkbox"/> B6846
-----------------------------------	-----------------------------------	--

LOCATION OF RELEASE

Unit Letter B	Section 20	Township 17S	Range 29E	Feet from the 330	North/South Line North	Feet from the 2310	East/West Line East	County <input type="checkbox"/> Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	--------------------------------------

NATURE OF RELEASE

Type of Release Oil & water	Volume of Release 3-5 bbls.	Volume Recovered <input type="checkbox"/>
Source of Release stuffing box leak	Date and Hour of Occurrence 02/23/04; 12:00 p.m.	Date and Hour of Discovery 02/23/04; 2:00 p.m.
Was Immediate Notice Given? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mr. Jerry Guy, NM OCD Field Representative	
By Whom? <input type="checkbox"/> Phillip Creech, Production Foreman	Date and Hour <input type="checkbox"/> 02/23/24; 2:02 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully. \*\*

RECEIVED

Describe Cause of Problem and Remedial Action Taken. \*

Stuffing Box leaked. Repair & replace rubbers on stuffing box.

MAR - 9 2004

OCD-ARTESIA

Describe Area Affected and Cleanup Action Taken. \*

Area affected: location around well head

Clean Up Action Taken: As per Mr. Guy's instructions, utilize back hoe to spread soil on ground surface, dig down to clean soil, and turn to remediate soil so that contaminates are within guideline levels.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

*Matt Swierc*

Printed Name: Matt Swierc

Approved by ☐ District Supervisor:

Title: Production Supt.

Approval Date:

Expiration Date:

Date: February 23, 2004

Phone: (432) 682-6324

Conditions of Approval:

Attached ☐

\* Attach Additional Sheets If Necessary