

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Momba 24 Federal Com #003H	Facility Type: Tank Battery
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-40946	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	24	26S	28E	43	North	2,180	East	Eddy

Latitude 32.0352135 Longitude -104.0392075

### NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 0.5 bbl. Oil & 12 bbl. PW	Volume Recovered: 0.25 bbl. Oil & 10 bbl. PW
Source of Release: Water Line	Date and Hour of Occurrence: August 15, 2017 1:00 pm	Date and Hour of Discovery: August 15, 2017 1:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The release was due to corrosion of a three-inch steel water line. The line was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The release occurred within the lined facility. A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Dakota Neel		Approved by Environmental Specialist: 	
Title: HSE Coordinator	Approval Date: 11/16/2022	Expiration Date:	
E-mail Address: dneel2@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: December 17, 2017 Phone: 575-746-2010			

\* Attach Additional Sheets If Necessary

**Abbott, Sam**

---

**From:** Dakota Neel  
**Sent:** Sunday, December 17, 2017 3:18 PM  
**To:** 'Weaver, Crystal, EMNRD'; stucker@blm.gov  
**Cc:** Bratcher, Mike, EMNRD; Jim Amos (jamos@blm.gov); Rebecca Haskell; Robert McNeill; Sheldon Hitchcock; Christopher Gray  
**Subject:** (C-141 Final) Momba 24 Federal Com #003H Tank Battery 8-15-17 (30-015-40946) 2RP-4350  
**Attachments:** Momba 24 Federal Com #003H Tank Battery Final C-141 8-15-17 (30-015-40946).pdf

Ms. Weaver/Ms. Tucker,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. There was precipitation falling during the final inspection pictures. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



---

**From:** Weaver, Crystal, EMNRD [mailto:Crystal.Weaver@state.nm.us]  
**Sent:** Tuesday, September 19, 2017 1:13 PM  
**To:** Rebecca Haskell; stucker@blm.gov  
**Cc:** Bratcher, Mike, EMNRD; Jim Amos (jamos@blm.gov)  
**Subject:** [External] RE: (C-141 Initial) Momba 24 Federal Com #003H Tank Battery 8-15-17 (30-015-40946)

\*\*\*\* External email. Use caution. \*\*\*\*

RE: COG \* Momba 24 Federal COM #3H \* 30-015-40946 \* 2RP-4350

Becky,

Sorry for the delay on sending this one out. I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4350. Please remit a site characterization plan or advise OCD of plan of action by no later than 9/30/17.

Thank you,

## Crystal Weaver

Environmental Specialist  
OCD – Artesia District II  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
Office: 575-748-1283 ext. 101  
Cell: 575-840-5963  
Fax: 575-748-9720

---

**From:** Rebecca Haskell [<mailto:RHaskell@concho.com>]  
**Sent:** Thursday, August 17, 2017 11:51 AM  
**To:** Weaver, Crystal, EMNRD <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>; [stucker@blm.gov](mailto:stucker@blm.gov)  
**Cc:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Jim Amos ([jamos@blm.gov](mailto:jamos@blm.gov)) <[jamos@blm.gov](mailto:jamos@blm.gov)>  
**Subject:** (C-141 Initial) Momba 24 Federal Com #003H Tank Battery 8-15-17 (30-015-40946)

Ms. Weaver / Ms. Tucker,

Please see the attached Initial C-141 for your consideration. If you have any questions or concerns please contact me.

Thank You,

Becky Haskell  
Senior HSE Coordinator  
COG Operating LLC  
600 W Illinois Avenue | Midland, TX 79701  
Direct: 432-818-2372 | Main: 432.683.7443  
Cell: 432-556-5130  
[rhaskell@concho.com](mailto:rhaskell@concho.com)



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this

email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 159458

**CONDITIONS**

Operator: COG PRODUCTION, LLC 600 W. Illinois Ave Midland, TX 79701	OGRID: 217955
	Action Number: 159458
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

**CONDITIONS**

Created By	Condition	Condition Date
amaxwell	None	11/16/2022