District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2301926781
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party San Mateo Midstream	OGRID 329461
Contact Name Arsenio Jones	Contact Telephone 575-361-4333
Contact email arsenio.jones@matadorresources.com	Incident # *(assigned by OCD)* nAPP2301926781
Contact mailing address 5400 LBJ Freeway, Suite 1500 Dallas, Texas 75240	

Location of Release Source

Latitude 32.025817 Longitude -103.703411
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Derna Booster Station	Site Type Booster Station
Date Release Discovered 01/18/2023	API# *(if applicable)*

Unit Letter	Section	Township	Range	County
L	20	26S	32E	Lea

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (*Name:* _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

☐ Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
☒ Produced Water	Volume Released (bbls) 13.5	Volume Recovered (bbls) 2.5
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	☐ Yes ☐ No
☐ Condensate	Volume Released (bbls)	Volume Recovered (bbls)
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
☐ Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Line at tie in failed

State of New Mexico
Oil Conservation Division

Incident ID	nAPP2301926781
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? ☐ Yes ☒ No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

☒ The source of the release has been stopped.

☒ The impacted area has been secured to protect human health and the environment.

☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

☒ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Arsenio Jones Title: Supervisor - Regulatory

Signature: Arsenio Jones Date: 01/18/2023

email: arsenio.jones@matadorresources.com Telephone: 575-361-4333

OCD Only

Received by: Jocelyn Harimon Date: 01/19/2023

Release Volume Estimation Equation

NAPP2301926781

Equation (1) Inputs	(LxW)/43560sqft	Equation (1) Assumptions
		1acre =43560 sqft

Area [ ] Length (ft) [ ] Width (ft) 0.3800 Acres

Equation (2) Inputs	Ksat*27,154gal/(42gal)	Equation (2) Assumptions
		1acre/inch =27,154 gal
		1bbl = 42gal

Ksat 0.1 in Inches per hour located at https://websoilsurvey.nrcs.usda.gov

64.65 BBL/Acre/hr

Equation (3)	(Eq2)X(Eq1) Area adjusted volume

24.57 BBl/hr max

Equation (4) Inputs	(Eq3)X release duration (hours)+recovered volume	Equation (4) Assumptions
		recovered fluids are not in soil solution

70 BBL

0.41 Duration (hr)

80.07 BBL

[1] infiltratration rate. The rate at which water penetrates the surface of the soil at any given instant, usually expressed in inches per hour. The rate can be limited by the infiltration capacity of the soil or the rate at which water is applied at the surface: (National Soil Survey Handobook (USDA)

[2] (Ksat) Hydraulic Conductivity. (National Soil Survey Handobook (USDA) conductivity is often referred to as coefficient of permeability, most commonly shortened to permeability

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 177384

CONDITIONS

Operator: MATADOR PRODUCTION COMPANY One Lincoln Centre Dallas, TX 75240	OGRID: 228937
	Action Number: 177384
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
jharimon	None	1/19/2023