



Certificate of Analysis

Number: 6030-21100297-009A

Artesia Laboratory

200 E Main St.
Artesia, NM 88210
Phone 575-746-3481Zach LaCount
Mewbourne Oil Company
4801 Business Park Blvd
Hobbs, NM 88240

Nov. 04, 2021

Station Name: Fuller 13/24 Battery VRT

Station Number: N/A

Station Location: Mewbourne

Sample Point: VRT

Instrument: 6030_GC2 (Agilent GC-7890B)

Last Inst. Cal.: 09/13/2021 14:54 PM

Analyzed: 11/02/2021 08:02:38 by EJH

Sampled By: Michael Mirabal

Sample Of: Gas Spot

Sample Date: 10/28/2021 03:43

Sample Conditions: 40 psig Ambient: 71 °F

Effective Date: 10/28/2021 03:43

Method: GPA 2286

Cylinder No: 5030-01545

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.696 psia	
Hydrogen Sulfide	0.000	0.00000	0.000		GPM TOTAL C2+ 25.213
Nitrogen	1.901	1.88100	1.214		GPM TOTAL C3+ 18.991
Methane	14.878	14.71800	5.442		GPM TOTAL iC5+ 4.584
Carbon Dioxide	0.182	0.18000	0.183		
Ethane	23.174	22.92500	15.888	6.222	
Propane	28.562	28.25500	28.716	7.900	
Iso-butane	5.684	5.62300	7.532	1.867	
n-Butane	14.659	14.50100	19.425	4.640	
Iso-pentane	3.865	3.82300	6.357	1.419	
n-Pentane	4.155	4.11000	6.834	1.512	
Hexanes Plus	4.027	3.98400	8.409	1.653	
	101.087	100.0000	100.000	25.213	

Calculated Physical Properties

Relative Density Real Gas

Total

1.5231

C6+

3.1473

Calculated Molecular Weight

43.39

91.15

Compressibility Factor

0.9828

GPA 2172 Calculation:

Calculated Gross BTU per ft³ @ 14.696 psia & 60°F

Real Gas Dry BTU

2478

4939

Water Sat. Gas Base BTU

2435

4853

Ideal, Gross HV - Dry at 14.696 psia

2435.7

4938.7

Ideal, Gross HV - Wet

2393.2

0.000

Comments: H2S Field Content 0 ppm

Data reviewed by: Krystle Fitzwater, Laboratory Manager

Quality Assurance:

The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.



Certificate of Analysis

Number: 6030-21100297-009A

Artesia Laboratory

200 E Main St.
Artesia, NM 88210
Phone 575-746-3481Zach LaCount
Mewbourne Oil Company
4801 Business Park Blvd
Hobbs, NM 88240

Nov. 04, 2021

Station Name: Fuller 13/24 Battery VRT
Station Number: N/A
Station Location: Mewbourne
Sample Point: VRT
Analyzed: 11/04/2021 05:01:14 by EJHSampled By: Michael Mirabal
Sample Of: Gas Spot
Sample Date: 10/28/2021 03:43
Sample Conditions: 40 psig
Method: GPA 2286
Cylinder No: 5030-01545

Analytical Data

Components	Mol. %	Wt. %	GPM at 14.696 psia
Hydrogen Sulfide	0.000	0.000	
Nitrogen	1.881	1.214	
Methane	14.718	5.442	
Carbon Dioxide	0.180	0.183	
Ethane	22.925	15.888	6.222
Propane	28.255	28.716	7.900
Iso-Butane	5.623	7.532	1.867
n-Butane	14.501	19.425	4.640
Iso-Pentane	3.823	6.357	1.419
n-Pentane	4.110	6.834	1.512
i-Hexanes	1.172	2.276	0.478
n-Hexane	0.785	1.571	0.329
Benzene	0.055	0.100	0.016
Cyclohexane	0.354	0.687	0.122
i-Heptanes	0.708	1.531	0.292
n-Heptane	0.208	0.477	0.097
Toluene	0.058	0.126	0.020
i-Octanes	0.475	1.130	0.213
n-Octane	0.040	0.109	0.021
Ethylbenzene	0.004	0.005	0.001
Xylenes	0.026	0.073	0.010
i-Nonanes	0.069	0.204	0.036
n-Nonane	0.015	0.046	0.008
Decanes Plus	0.015	0.074	0.010
	100.000	100.000	25.213



Certificate of Analysis

Number: 6030-21100297-009A

Artesia Laboratory
200 E Main St.
Artesia, NM 88210
Phone 575-746-3481

Zach LaCount
Mewbourne Oil Company
4801 Business Park Blvd
Hobbs, NM 88240

Nov. 04, 2021

Station Name: Fuller 13/24 Battery VRT
Station Number: N/A
Station Location: Mewbourne
Sample Point: VRT
Analyzed: 11/04/2021 05:01:14 by EJR

Sampled By: Michael Mirabal
Sample Of: Gas Spot
Sample Date: 10/28/2021 03:43
Sample Conditions: 40 psig
Method: GPA 2286
Cylinder No: 5030-01545

Calculated Physical Properties	Total	C10+
Calculated Molecular Weight	43.39	152.79
GPA 2172 Calculation:		
Calculated Gross BTU per ft³ @ 14.696 psia & 60°F		
Real Gas Dry BTU	2478.2	8447.1
Water Sat. Gas Base BTU	2435.0	8157.2
Relative Density Real Gas	1.5231	5.2755
Compressibility Factor	0.9828	
Ideal, Gross HV - Wet	2393.2	
Ideal, Gross HV - Dry at 14.696 psia	2435.7	
Net BTU Dry Gas - real gas	2280	
Net BTU Wet Gas - real gas	2240	

Comments: H2S Field Content 0 ppm

Data reviewed by: Krystle Fitzwater, Laboratory Manager

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.

Mewbourne Oil Company

Natural Gas Flared Calculation Methodology

Metering low-pressure gas diverted from the Vapor Recovery Unit ("VRU") to backup flare is not technologically feasible. Gas volumes for VRU downtime events will be calculated using an average metered VRU gas to oil production ratio. This GOR is derived from available relevant data.

Average Metered VRU Gas to Oil Production GOR = 0.18 Mcf/BBL

Flared gas volume = GOR * Oil Production Volume (BBL)

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 233129

DEFINITIONS

Operator: MEWBOURNE OIL CO P.O. Box 5270 Hobbs, NM 88241	OGRID: 14744
	Action Number: 233129
	Action Type: [C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: • this application's operator, hereinafter "this operator"; • venting and/or flaring, hereinafter "vent or flare"; • any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms"; • the statements in (and/or attached to) this, hereinafter "the statements in this"; • and the past tense will be used in lieu of mixed past/present tense questions and statements.
--

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 233129

QUESTIONS

Operator: MEWBOURNE OIL CO P.O. Box 5270 Hobbs, NM 88241	OGRID: 14744
	Action Number: 233129
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Prerequisites Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.	
Incident Well	Unavailable.
Incident Facility	[fAPP2125737241] FULLER 13/12 BATTERY

Determination of Reporting Requirements Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.	
Was this vent or flare caused by an emergency or malfunction	Yes
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	VRU

Representative Compositional Analysis of Vented or Flared Natural Gas Please provide the mole percent for the percentage questions in this group.	
Methane (CH4) percentage	15
Nitrogen (N2) percentage, if greater than one percent	2
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (C02) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (C02) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

District I

1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 233129

QUESTIONS (continued)

Operator: MEWBOURNE OIL CO P.O. Box 5270 Hobbs, NM 88241	OGRID: 14744
	Action Number: 233129
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	06/22/2023
Time vent or flare was discovered or commenced	12:00 AM
Time vent or flare was terminated	08:00 AM
Cumulative hours during this event	8

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Equipment Failure Other (Specify) Natural Gas Flared Released: 55 Mcf Recovered: 0 Mcf Lost: 55 Mcf.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Volume calculated
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	No
Was notification of downstream activity received by this operator	Not answered.
Downstream OGRID that should have notified this operator	Not answered.
Date notified of downstream activity requiring this vent or flare	Not answered.
Time notified of downstream activity requiring this vent or flare	Not answered.

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	VRU malfunctioned
Steps taken to limit the duration and magnitude of vent or flare	Repaired VRU
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Continued routine preventive maintenance and daily operational inspections

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 233129

ACKNOWLEDGMENTS

Operator: MEWBOURNE OIL CO P.O. Box 5270 Hobbs, NM 88241	OGRID:	14744
	Action Number:	233129
	Action Type:	[C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

☒	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
☒	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
☒	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
☒	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
☒	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 233129

CONDITIONS

Operator: MEWBOURNE OIL CO P.O. Box 5270 Hobbs, NM 88241	OGRID: 14744
	Action Number: 233129
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
zlaount	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	6/27/2023