

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department  
  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	nAPP2319246735
District RP	
Facility ID	fAPP2132240047
Application ID	

## Release Notification

### Responsible Party

Responsible Party: Chevron U.S.A., Inc.	OGRID: 4323
Contact Name: Aaron Rotto	Contact Telephone: 281-543-3205
Contact email: aaron.rotto@chevron.com	Incident # nAPP2319246735
Contact mailing address: 6301 Deauville Blvd Midland, TX 79706	

### Location of Release Source

Latitude: 32.137253 \_\_\_\_\_ Longitude: -104.226084 \_\_\_\_\_  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Hayhurst 17/18 Tank Battery	Site Type: Oil
Date Release Discovered: 7/10/2023	API# (if applicable):

Unit Letter	Section	Township	Range	County
B	18	25S	27E	Artesia

Surface Owner:  State  Federal  Tribal  Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls): 7.398	Volume Recovered (bbls):
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls): 326.018	Volume Recovered (bbls): 310 (Total Fluid Oil and Water)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release:

4" ball valve separated on water load line.

Incident ID	nAPP2319246735
District RP	
Facility ID	fAPP2132240047
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?  Release over 25 bbl.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?  Aaron Rotto – Notified NMOCD (Laura Tolk) Via Phone on 07/11/2023 at 12:45 PM PST.	

### Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.
If all the actions described above have <u>not</u> been undertaken, explain why:   
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
Printed Name: <u>Aaron Rotto</u> Title: <u>Lead Environmental Specialist, Field Support</u> Signature: <u>Aaron C. Rotto</u> Date: <u>2/7/2023</u> email: <u>aaron.rotto@chevron.com</u> Telephone: <u>281-543-3205</u>
<b><u>OCD Only</u></b>  Received by: <u>Shelly Wells</u> Date: <u>7/12/2023</u>

Incident ID	nAPP2319246735
District RP	
Facility ID	fAPP2132240047
Application ID	

Spill Calculations:

**Reported Volumes**

**Oil Released: 7.398bbl**

**Oil Recovered: bbl**

**Water Released: 326.018bbl**

**Water Recovered: bbl**

Calculation Details

Area 1

Shape: Rectangle

Secondary Containment?: No

Standing Liquid Dimensions: 117 ft x 13 ft x 6 in

Total Volume: 135.450 bbl

Water Cut: 96%

Oil Volume: 5.418 bbl

Penetration Depth: 0 in

Fluid to Soil Volume: .000 bbl

Water Volume: 130.032 bbl

Area 2

Shape: Rectangle

Secondary Containment?: No

Standing Liquid Dimensions: 81 ft x 13 ft x 6 in

Total Volume: 93.773 bbl

Water Cut: 99%

Oil Volume: .938 bbl

Penetration Depth: 0 in

Volume to Soil Volume: .000 bbl

Water Volume: 92.835 bbl

Area 3

Shape: Rectangle

Secondary Containment?: No

Standing Liquid Dimensions: 90 ft x 13 ft x 6 in

Total Volume: 104.193 bbl

Water Cut: 99%

Oil Volume: 1.042 bbl

Penetration Depth: 0 in

Fluid to Soil Volume: .000 bbl

Water Volume: 103.151 bbl

**District I**  
 1625 N. French Dr., Hobbs, NM 88240  
 Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**  
 811 S. First St., Artesia, NM 88210  
 Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**  
 1220 S. St Francis Dr., Santa Fe, NM 87505  
 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 238618

**CONDITIONS**

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 238618
	Action Type: [C-141] Release Corrective Action (C-141)

**CONDITIONS**

Created By	Condition	Condition Date
scwells	None	7/12/2023