

Form C-141

Page 6

State of New Mexico
Oil Conservation Division

Incident ID	nAPP2323049703
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: *Each of the following items must be included in the closure report.*

- ☒ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☒ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☒ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Kevin Smith Title: Sr. Operations ManagerSignature: Kevin Smith Digitally signed by Kevin Smith
DN: cn=Kevin Smith, email=kevin.smith@targaresources.com, o=Targare Resources, ou=Oil Conservation Division, cn=Kevin Smith
Date: 2023.10.23 17:48:51-0500 Date: 10-23-2023email: kevin.smith@targaresources.com Telephone: (817)975-3725**OCD Only**Received by: Shelly Wells Date: 10/24/2023

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: Shelly Wells Date: 10/25/2023Printed Name: Shelly Wells Title: Environmental Specialist-Advanced



Targa Midstream Services LLC
6 Desta Drive, Suite 3300
Midland, TX 79705
432.688.0555
www.targaresources.com

October 19, 2023

New Mexico Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Re: NMOCD #nAPP2323049703
Red Hills Gas Plant
32.213895, -103.523733
U/L O, Section 13, Township 24 South, Range 33 East


Dear Sir or Madam:

An unexpected fire occurred on August 18, 2023 at Red Hills Gas Plant. The cause of this event was a leak on a third party vacuum truck working in the plant. The gas leak from the vacuum truck migrated to a nearby maintenance truck and ignited. The fire caused property damage to the water flash tank and water flash tank support. Third party emergency personnel extinguished the fire.

Sincerely,

Amber Groves
Sr. Environmental Specialist
Targa Midstream Services LLC

Red Hills Map



Green Circle Indicates Fire Location

Red Hills Photo Documentation



Photo of Property Damage to water flash tank and support



Photo of property damage to water flash tank and support



Photo of third party vacuum truck and mechanic truck

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 278629

CONDITIONS

Operator: Targa Northern Delaware, LLC. 110 W. 7th Street, Suite 2300 Tulsa, OK 74119	OGRID: 331548
	Action Number: 278629
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
scwells	None	10/25/2023