

Form C-141

Page 6

State of New Mexico  
Oil Conservation Division

Incident ID	nAPP23242553643
District RP	
Facility ID	
Application ID	


## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

**Closure Report Attachment Checklist:** *Each of the following items must be included in the closure report.*

- ☒ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☒ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☒ Laboratory analyses of final sampling (Note: appropriate OCD District office must be notified 2 days prior to final sampling)
- ☒ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Jason Fuentes Title: Area Manager  
Signature:  Date: 11-30-23  
email: jason.fuentes@targaresources.com Telephone: (575)365-8939

**OCD Only**

Received by: \_\_\_\_\_ Date: \_\_\_\_\_

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: \_\_\_\_\_ Date: \_\_\_\_\_

Printed Name: \_\_\_\_\_ Title: \_\_\_\_\_



Targa Midstream Services LLC  
6 Desta Drive, Suite 3300  
Midland, TX 79705  
432.688.0555  
[www.targaresources.com](http://www.targaresources.com)

November 14, 2023

New Mexico Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Re: NMOCD #nAPP232453643  
Cabo Wabo Compressor Station  
32.136949, -103.937503  
U/L B, Section 13, Township 25 South, Range 29 East

Dear Sir or Madam:

An incident occurred on August 30, 2023 at Targa's Cabo Wabo Compressor Station when a fire occurred on a third party diesel air compressor. The cause of the unexpected fire on the diesel air compressor was inconclusive. The fire caused property damage to the diesel air compressor. There was no damage to any Targa equipment. Emergency services personnel were called and extinguished the fire.

Sincerely,

Amber Groves  
Sr. Environmental Specialist  
Targa Midstream Services LLC



**Cabo Wabo Photo Page**



**View of Generator Post-Fire**



**View of Generator Post Fire**



CABO WABO EQUIPMENT LIST	
ITEM	DESCRIPTION
C-101	3606 COMPRESSOR
C-102	3606 COMPRESSOR
C-103	3606 COMPRESSOR
C-104	3606 COMPRESSOR
C-105	3606 COMPRESSOR
C-106	3606 COMPRESSOR
C-107	3606 COMPRESSOR
C-108	3606 COMPRESSOR
V-101	SLUG CATCHER
V-102	FILTER SEPARATOR
V-103	3 PHASE SEPARATOR
V-104	BLOWCASE
V-105	TEG AFTER SCRUBBER
V-106	FUEL GAS SCRUBBER
V-107	VENT SEPARATOR
BTEX	BTEX
T-100	GLYCOL CONTACTOR
RG-300	1.5 MMBTU GLYCOL REGENERATION UNIT
TK-101	CONDENSATE TANK
TK-102	WASTE WATER TANK
TK-103	WASTE WATER TANK
R-200	20"x16" PIG RECEIVER
L-201	16"x12" PIG LAUNCHER

REFERENCE DWGS.	REV	DESCRIPTION	DWN	CHKD	DATE	REV	DESCRIPTION	DWN	CHKD	DATE	SCALE:	NONE	DATE
											DWN BY:	SSH	01/2023
											CHKD BY:	CSS	01/2023
											FINAL CK:		
											ENGR.:	CSS	01/2023
						A	PRELIMINARY				APPRV:		
This drawing is owned by a TARGA Resources, Inc. operating subsidiary and is loaned solely for confidential use. Recipient promises and agrees to return this drawing upon request and agrees that it shall not be reproduced, copied, loaned or otherwise disposed of, nor used for any purpose other than that for which it is furnished without express written consent. NO REPRESENTATION OR WARRANTY IS MADE REGARDING THE ACCURACY OF THIS DRAWING IN ANY PARTICULAR.											PLANT NAME		
PREPARED BY: TARGA TECHNICAL SERVICES											SUPREME		
PROJECT NUMBER: -											OFFLOAD METERING SITE		



SHEET 1 OF 1

DRAWING NUMBER	2205-400
CAD FILE NAME	2205-400
REVISION	A

PLOT PLAN  
CABO WABO COMPRESSOR STATION  
LEA COUNTY, NEW MEXICO

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 289948

CONDITIONS

Operator: Targa Northern Delaware, LLC. 110 W. 7th Street, Suite 2300 Tulsa, OK 74119	OGRID: 331548
	Action Number: 289948
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
scwells	None	3/19/2024