

**District I**

1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 362371

**QUESTIONS**

Operator: Murchison Oil and Gas, LLC 7250 Dallas Parkway Plano, TX 75024	OGRID:
	15363
	Action Number:
	362371
Action Type:	
[NOTIFY] Notification Of Liner Inspection (C-141L)	

**QUESTIONS**

Prerequisites	
Incident ID (n#)	nAPP2415754364
Incident Name	NAPP2415754364 CARBON VALLEY 25 FEDERAL COM #007H @ 30-015-38060
Incident Type	Other
Incident Status	Initial C-141 Approved
Incident Well	[30-015-38060] CARBON VALLEY 25 FEDERAL COM #007H

**Location of Release Source**

Site Name	Carbon Valley 25 Federal Com #007H
Date Release Discovered	04/16/2013
Surface Owner	Federal

**Liner Inspection Event Information***Please answer all the questions in this group.*

What is the liner inspection surface area in square feet	10,000
Have all the impacted materials been removed from the liner	Yes
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	07/12/2024
Time liner inspection will commence	09:30 AM
Please provide any information necessary for observers to liner inspection	Please contact dimitry@mcnabbpartners.com if needed. 917-497~6890
Please provide any information necessary for navigation to liner inspection site	GPS coordinates: 32.8983695, -104.239828

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 362371

CONDITIONS

Operator: Murchison Oil and Gas, LLC 7250 Dallas Parkway Plano, TX 75024	OGRID: 15363
	Action Number: 362371
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
aparkermp	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	7/9/2024