

***** LIQUID SPILLS - VOLUME CALCULATIONS *****

Location of Spill: LEAMEX #015

Date of Spill: 3/16/2005

If the leak/spill is associated with production equipment, i.e. - wellhead, stuffing box, flowline, tank battery, production vessel, transfer pump, or storage tank place an "X" here:

Input Data:

If spill volumes from measurement, i.e. metering, tank volumes, etc. are known enter the volumes here: OIL: 14.0000 BBL WATER: 1.0000 BBL

If "known" spill volumes are given, input data for the following "Area Calculations" is optional. The above will override the calculated volumes.

| Total Area Calculations | | | | | Standing Liquid Calculations | | | | |
|-------------------------|-----------|-----------|----------------|---------|------------------------------|-----------|-----------|--------------|---------|
| Total Surface Area | width | length | wet soil depth | oil (%) | Standing Liquid Area | width | length | liquid depth | oil (%) |
| Rectangle Area #1 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% | Rectangle Area #1 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% |
| Rectangle Area #2 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% | Rectangle Area #2 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% |
| Rectangle Area #3 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% | Rectangle Area #3 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% |
| Rectangle Area #4 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% | Rectangle Area #4 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% |
| Rectangle Area #5 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% | Rectangle Area #5 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% |
| Rectangle Area #6 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% | Rectangle Area #6 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% |
| Rectangle Area #7 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% | Rectangle Area #7 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% |
| Rectangle Area #8 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% | Rectangle Area #8 | 0.00 ft X | 0.00 ft X | 0.00 in | 0.00% |

production system leak - DAILY PRODUCTION DATA REQUIRED

Average Daily Production: Oil BBL Water BBL

Did leak occur before the separator?: YES N/A (place an "X")

Amount of Free Liquid Recovered: 1 BBL **ERROR - Recovered volume greater than spilled volume** Percentage of Oil in Free Liquid Recovered: ##### (percentage)

Liquid holding factor *: 0.08 gal per gal

Use the following when the spill wets the grains of the soil:
 * sand = .08 gallon liquid per gallon volume of soil.
 * gravelly (caliche) loam = .14 gallon liquid per gallon volume of soil.
 * sandy clay loam soil = .14 gallon liquid per gallon volume of soil.
 * clay loam = .16 gallon liquid per gallon volume of soil.

Use the following when the liquid completely fills the pore space of the soil:
 Occurs when the spill soaked soil is contained by barriers, natural (or not).
 * gravelly (caliche) loam = .25 gallon liquid per gallon volume of soil.
 * sandy loam = .5 gallon liquid per gallon volume of soil.

Saturated Soil Volume Calculations:

Free Liquid Volume Calculations:

| Total Solid/Liquid Volume: | sq. ft. | H2O cu. ft. | OIL cu. ft. | Total Free Liquid Volume: | sq. ft. | H2O cu. ft. | OIL cu. ft. |
|----------------------------------|---------|--------------|-------------|--|---------|-------------|-------------|
| Estimated Volumes Spilled | | H2O | OIL | Estimated Production Volumes Lost | | H2O | OIL |
| Liquid in Soil: | | 0.0 BBL | 0.0 BBL | Estimated Production Spilled: | | 1.0 BBL | 14.0 BBL |
| Free Liquid: | | 0.0 BBL | 0.0 BBL | Estimated Surface Damage | | | |
| Totals: | | 0.0 BBL | 0.0 BBL | Surface Area: <u> </u> sq. ft. | | | |
| Total Spill Liquid: | | 1.0 BBL | 14.0 BBL | Surface Area: <u>.0000</u> acre | | | |
| Recovered Volumes | | | | Estimated Weights, and Volumes | | | |
| Estimated oil recovered: | 1.0 BBL | check - okay | | Saturated Soil = <u> </u> lbs | | cu.ft. | cu.yds. |
| Estimated water recovered: | 0.0 BBL | check - okay | | Total Liquid = <u>15</u> BBL | | 630 gallon | 5,242 lbs |

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720
District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720
District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 362806

QUESTIONS

| | |
|--|---|
| Operator: Maverick Permian LLC 1000 Main Street, Suite 2900 Houston, TX 77002 | OGRID: 331199 |
| | Action Number: 362806 |
| | Action Type: [C-141] Initial C-141 (C-141-v-Initial) |

QUESTIONS

| | |
|----------------------|---|
| Prerequisites | |
| Incident ID (n#) | nPRS0520747681 |
| Incident Name | NPRS0520747681 LEAMEX #015 @ 30-025-23135 |
| Incident Type | Oil Release |
| Incident Status | Initial C-141 Received |
| Incident Well | [30-025-23135] LEAMEX #015 |

| | |
|---|-------------|
| Location of Release Source | |
| <i>Please answer all the questions in this group.</i> | |
| Site Name | LEAMEX #015 |
| Date Release Discovered | 03/16/2005 |
| Surface Owner | State |

| | |
|--|-------------|
| Incident Details | |
| <i>Please answer all the questions in this group.</i> | |
| Incident Type | Oil Release |
| Did this release result in a fire or is the result of a fire | No |
| Did this release result in any injuries | No |
| Has this release reached or does it have a reasonable probability of reaching a watercourse | No |
| Has this release endangered or does it have a reasonable probability of endangering public health | No |
| Has this release substantially damaged or will it substantially damage property or the environment | No |
| Is this release of a volume that is or may with reasonable probability be detrimental to fresh water | No |

| | |
|---|--|
| Nature and Volume of Release | |
| <i>Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.</i> | |
| Crude Oil Released (bbls) Details | Cause: Corrosion Flow Line - Production Crude Oil Released: 14 BBL Recovered: 1 BBL Lost: 13 BBL. |
| Produced Water Released (bbls) Details | Cause: Corrosion Flow Line - Production Produced Water Released: 1 BBL Recovered: 0 BBL Lost: 1 BBL. |
| Is the concentration of chloride in the produced water >10,000 mg/l | Yes |
| Condensate Released (bbls) Details | Not answered. |
| Natural Gas Vented (Mcf) Details | Not answered. |
| Natural Gas Flared (Mcf) Details | Not answered. |
| Other Released Details | Not answered. |
| Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts) | Not answered. |

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 362806

QUESTIONS (continued)

| | |
|--|---|
| Operator: Maverick Permian LLC 1000 Main Street, Suite 2900 Houston, TX 77002 | OGRID: 331199 |
| | Action Number: 362806 |
| | Action Type: [C-141] Initial C-141 (C-141-v-Initial) |

QUESTIONS

| | |
|---|--|
| Nature and Volume of Release (continued) | |
| Is this a gas only submission (i.e. only significant Mcf values reported) | No, according to supplied volumes this does not appear to be a "gas only" report. |
| Was this a major release as defined by Subsection A of 19.15.29.7 NMAC | No |
| Reasons why this would be considered a submission for a notification of a major release | <i>Unavailable.</i> |

With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e. gas only) are to be submitted on the C-129 form.

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury.

| | |
|--|----------------------|
| The source of the release has been stopped | True |
| The impacted area has been secured to protect human health and the environment | True |
| Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices | True |
| All free liquids and recoverable materials have been removed and managed appropriately | True |
| If all the actions described above have not been undertaken, explain why | <i>Not answered.</i> |

Per Paragraph (4) of Subsection B of 19.15.29.8 NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of actions to date in the follow-up C-141 submission. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC), please prepare and attach all information needed for closure evaluation in the follow-up C-141 submission.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | |
|--|--|
| I hereby agree and sign off to the above statement | Name: Chuck Terhune Title: Program Manager Email: chuck.terhune@tetrattech.com Date: 07/10/2024 |
|--|--|

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720
District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720
District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 3

Action 362806

QUESTIONS (continued)

| | |
|--|--|
| Operator: Maverick Permian LLC 1000 Main Street, Suite 2900 Houston, TX 77002 | OGRID: 331199 Action Number: 362806 Action Type: [C-141] Initial C-141 (C-141-v-Initial) |
|--|--|

QUESTIONS

Site Characterization
 Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

| | |
|--|--------------------------------|
| What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs) | Between 100 and 500 (ft.) |
| What method was used to determine the depth to ground water | Estimate or Other |
| Did this release impact groundwater or surface water | No |
| What is the minimum distance, between the closest lateral extents of the release and the following surface areas: | |
| A continuously flowing watercourse or any other significant watercourse | Greater than 5 (mi.) |
| Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark) | Between 1000 (ft.) and ½ (mi.) |
| An occupied permanent residence, school, hospital, institution, or church | Between 1 and 5 (mi.) |
| A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes | Between 1 and 5 (mi.) |
| Any other fresh water well or spring | Between 1 and 5 (mi.) |
| Incorporated municipal boundaries or a defined municipal fresh water well field | Greater than 5 (mi.) |
| A wetland | Between 1000 (ft.) and ½ (mi.) |
| A subsurface mine | Greater than 5 (mi.) |
| An (non-karst) unstable area | Greater than 5 (mi.) |
| Categorize the risk of this well / site being in a karst geology | Low |
| A 100-year floodplain | Greater than 5 (mi.) |
| Did the release impact areas not on an exploration, development, production, or storage site | No |

| | |
|--|----|
| Remediation Plan | |
| Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date. | |
| Requesting a remediation plan approval with this submission | No |
| The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required. | |

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 362806

CONDITIONS

| | |
|--|---|
| Operator: Maverick Permian LLC 1000 Main Street, Suite 2900 Houston, TX 77002 | OGRID: 331199 |
| | Action Number: 362806 |
| | Action Type: [C-141] Initial C-141 (C-141-v-Initial) |

CONDITIONS

| Created By | Condition | Condition Date |
|------------|---|----------------|
| amaxwell | Accepted for record only. An initial C141 was received 7/26/2005. | 7/12/2024 |
| amaxwell | This release is currently out of compliance. A report is due October 4, 2024. Failure to submit a complete report by October 4, 2024 may result in compliance and enforcement penalties pursuant to 19.15.5 NMAC. | 7/12/2024 |