

From: [Bratcher, Mike, EMNRD](#)
To: heather.dolphin@memorialrd.com
Cc: [Morales, Tony, EMNRD](#); [Patterson, Heather, EMNRD](#)
Subject: FW: Leak-Stained Area 32.8436040/103.9618074 Holly Energy Partners
Date: Monday, October 05, 2015 8:37:13 AM
Attachments: 001.jpg
002.jpg
003.jpg
004.jpg
005.jpg
006.jpg

Good Morning Heather,

One of our field inspectors came across this release last week near a Memorial well site. He thought it may be from an adjacent Holly line, but typically, Holly will have oil only and this looks to be mostly produced water. Would you please have your field folks check it out or give me contact information for someone here that could help?

Thank you,

Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

-----Original Message-----

From: Morales, Tony, EMNRD
Sent: Monday, October 05, 2015 8:05 AM
To: Bratcher, Mike, EMNRD
Cc: Patterson, Heather, EMNRD; Dade, Randy, EMNRD; Morales, Tony, EMNRD
Subject: Leak-Stained Area 32.8436040/103.9618074 Holly Energy Partners

MR. BRATCHER

FYI:

LEAK AREA 32.8436040/103.9618074 STAINED AREA APPROXIMATELY 5' X 45' LEAK RAN INTO GULLY-WASH OUT AREA. NEAREST LOCATION LOCO HILLS FEDERAL A 002 . LEAK WAS NOT FROM THAT LOCATION. THANK YOU.

Tony Morales, Compliance Officer
EMNRD-OCD
811 S. First St.
Artesia, NM 88210
575-748-1283 ext. 106
575-703-0233 (cellular)
Tony.Morales@state.nm.us

Your message is ready to be sent with the following file or link attachments:

001.jpg
002.jpg
003.jpg
004.jpg
005.jpg
006.jpg

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.













From: [Heather Dolphin](#)
To: [Bratcher, Mike, EMNRD](#)
Cc: [Morales, Tony, EMNRD](#); [Patterson, Heather, EMNRD](#)
Subject: RE: Leak-Stained Area 32.8436040/103.9618074 Holly Energy Partners
Date: Monday, October 05, 2015 3:16:14 PM
Attachments: 9-25-15 Loco Hills A-2 25bbIsPW.XLSX

Mike, Please see attached the incident report and C-141 filed at the time of spill when not all the details were clear. I thought it was at the Burnham Lease, but it was at Loco Hills. I will send the corrected C-141 following this email.

Below is the contact person for this spill - and you are always welcome to call me.

Chris Gafford, EHS Specialist
Direct (432) 218-8642
Mobile (432) 288-2030
chris.gafford@memorialrd.com

Thank You

Heather Dolphin
Sr. Regulatory Specialist
Memorial Resource Development Corp.
500 Dallas Street, Suite 1800
Houston, TX 77002
Direct (832) 408-8603
Mobile (832)-797-1334
Main (713) 588-8300
Fax (713) 588-8301
heather.dolphin@memorialrd.com

-----Original Message-----

From: Bratcher, Mike, EMNRD [<mailto:mike.bratcher@state.nm.us>]
Sent: Monday, October 05, 2015 9:37 AM
To: Heather Dolphin <heather.dolphin@memorialrd.com>
Cc: Morales, Tony, EMNRD <Tony.Morales@state.nm.us>; Patterson, Heather, EMNRD <Heather.Patterson@state.nm.us>
Subject: FW: Leak-Stained Area 32.8436040/103.9618074 Holly Energy Partners

Good Morning Heather,

One of our field inspectors came across this release last week near a Memorial well site. He thought it may be from an adjacent Holly line, but typically, Holly will have oil only and this looks to be mostly produced water. Would you please have your field folks check it out or give me contact information for someone here that could help?

Thank you,

Mike Bratcher
NMOCD District 2

811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

-----Original Message-----

From: Morales, Tony, EMNRD
Sent: Monday, October 05, 2015 8:05 AM
To: Bratcher, Mike, EMNRD
Cc: Patterson, Heather, EMNRD; Dade, Randy, EMNRD; Morales, Tony, EMNRD
Subject: Leak-Stained Area 32.8436040/103.9618074 Holly Energy Partners

MR. BRATCHER

FYI:

LEAK AREA 32.8436040/103.9618074 STAINED AREA APPROXIMATELY 5' X 45' LEAK RAN INTO GULLY-WASH OUT AREA. NEAREST LOCATION LOCO HILLS FEDERAL A 002 . LEAK WAS NOT FROM THAT LOCATION. THANK YOU.

Tony Morales, Compliance Officer
EMNRD-OCD
811 S. First St.
Artesia, NM 88210
575-748-1283 ext. 106
575-703-0233 (cellular)
Tony.Morales@state.nm.us

Your message is ready to be sent with the following file or link attachments:

001.jpg
002.jpg
003.jpg
004.jpg
005.jpg
006.jpg

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

		Incident Report Form <small>IRF V2</small>		Area: 5. Permian Basin Field: Loco Hills Group: Production Location: Loco Hills A-2 Supervisor: Emory Mann Sr.	
Please fill in all pertinent information (Where applicable, select from dropdown). IF Vehicle Incident, you will also need to complete the "Auto Accident" Tab OR submit a copy of the Auto Accident Form located in the glove box of all Company Vehicles.					
1. General Information		Main Incident Type:		Spill	
Safety Incident:	No	Environmental Incident:	Yes	Regulatory/Compliance Incident:	Yes
Other:	No				
Employee:	No	Contractor:	No	Third Party:	No
Property Only:	Yes	Non-work Related: No			
Person-In-Charge(PIC): Emory Mann, Sr.			PIC Phone: 575.420.8393		
Report Date: 9-Oct-15		Report Time (AM/PM):		7:44 PM	
Name/Title of Person Completing Report: Chris Gafford / EHS Specialist			Phone: 432.288.2030		
Name/Title of Person that discovered the incident:			Robin Goodrich / Lease Operator / 575.308.2012		
Date and Time incident occurred/discovered:		Date: 09/27/15		Time (AM/PM): 8:00 PM	
2. Incident Summary					
Please do not use all capital letters. Attach documents if more space is needed.					
The injection line going to the Loco Hills A-2 developed a hole due to corrosion. The line is buried about 4ft. deep. The fluid bubbled up to surface and ended up spilling approx. 25bbls of PW in the pasture. The fluid was a 60'x1' stream with a 10ft. Pool at the end. Most of the spill was on location with about 20' of it in the pasture. Line was replaced. BLM has been notified. Waiting on clean-up instructions from BLM/OCD.					
Working Activity:		Operations-Field Production		Incident related to: Tools/Equipment	
3. Location					
Location:(name/description)		Loco Hills		API/State ID #	
State: New Mexico		County/Parish: Eddy		Well #: A-2	
Longitude:		Latitude:		Rig#	
Nearest Town (Name, distance and direction from the incident)			2 miles NE of Loco Hills		
4. Weather/Site Conditions					
Describe the condition of the ground:		Dry, caliche, pasture, sand			
Temperature: 95		Describe the weather: Dry, dark			
Wind Speed: 5		Did Weather affect this incident?		NO	
5. Contractor Information-if more than one contractor is involved, provide an attachment with the list of additional contractors.					
Company Name					
Address:					
Point of Contact:		Title:		Phone#	
6. Third Party Involvement/Complaint Impact					
Name:		Third Party Phone#:			
Driver's License #:		Driver License State:			
Vehicle Plate #:		Vehicle State:		Ins Co Name:	
Ins.Policy #		Company Name		Ins Phone#	
7. Injury/Illness (Employee or Contractor)-					
Name:		E/C		Years of Experience:	
Work Phone #:		Home#:		Occupation	
How did injury/illness occur?					
Primary body Part Injured:		Equipment:			

Injury Resulted from:		Injury Type:	
Injury/Illness Category:		Illness Type:	
Did the person receive Professional Medical Treatment?			
Hospital/Clinic		Address:	
Phone#	Doctor's name:	Phone#	
Describe treatment:			
8. Vehicle Incident		# of Vehicles?	Collision Type:
Driver's Name:	DL#	DL State:	
MRD Vehicle #	If injuries, complete no.6 and/or 7 above.		
Witness Name:	Witness phone number:		
Was the incident covered by DOT?		Preventable:	Cause related to:
Was a citation issued?		Distraction:	
9. Equipment Damage		MRD	Non-MRD
10. Spills and Air Releases		Cause: Mechanical Failure	
Materials Released	Oil No	Produced Water Yes	Gas No
Quantity released:	Oil	Produce Water	Quantity recovered
(report all liquids in bbls)	Chemical	Other:	Chemical
Size of Affected area:	60'x1' stream w/ 10ft pool		Chemicals Spilled:
Total Time of Air Release:	Start:	End:	Gas Released:
Describe area, Property, and Wildlife impacted:			
Some of the fluid got into the pasture and sand			
Immediate Concern:	Wildlife Affect	Reportable to Regulator?	Yes
Describe Immediate Actions Taken:			
Line was shut off that night. Replaced the next day.			
11. Corrective Actions- Number Corrective Actions (1,2,3...)			
Control box is for Controls/Events	Preventive/Corrective Action	Responsible MRD Employee	Due Date
Supervision	Injection line was replaced in the corroded area.	Emory Mann, Sr. / Foreman / 575.420.8393	9/26/2015
			Completion Date
			9/26/2015
12. Contact Log (Enter Agency information in the bottom two rows)			
Date:	Person or Agency Notified	Time	Phone Number
09/26/15	Chris Gafford		432.288.2030
09/26/15	Steve Tadlock		956.489.1773
			Email address/Fax
09/26/15	Emory Mann Sr.		575.420.8393
09/26/15	heather Dolphin		832.408.8603
09/26/15	Heather reported to BLM		

Submit completed report electronically to the EHS Department.

From: [Tucker, Shelly](#)
To: [Heather Dolphin](#)
Cc: [Arias, Arthur](#); [Bratcher, Mike, EMNRD](#); [Patterson, Heather, EMNRD](#)
Subject: Re: Memorial Burnham Battery Spill
Date: Wednesday, October 07, 2015 8:33:30 AM

You need to sample and delineate the spill area. I also need to send some kind of map/drawing showing the impacted area and sample points. After gathering your analytical data, please submit the type of a clean-up you desire to perform and I will review it. I need to know the area in which it impacted the pasture to verify Arch.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist
Bureau of Land Management

620 E. Greene St
Carlsbad, NM 88220

575.234.5905 - Direct
575.361.0084 - Cellular

stucker@blm.gov



On Tue, Oct 6, 2015 at 1:22 PM, Heather Dolphin <heather.dolphin@memorialrd.com> wrote:

Depending on the spill we have been directed to scrape and resurface ourselves, or submit work plan and delineate, or pay arch fees. So we have come custom to waiting on direction from BLM/OCD. Memorial does not want to hire an environmental company for every spill as this becomes very costly.

Thank You

From: Tucker, Shelly [mailto:stucker@blm.gov]
Sent: Tuesday, October 06, 2015 10:42 AM

To: Heather Dolphin <heather.dolphin@memorialrd.com>
Cc: Arias, Arthur <aaarias@blm.gov>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>;
Patterson, Heather, EMNRD <Heather.Patterson@state.nm.us>

Subject: Re: Memorial Burnham Battery Spill

I was reviewing your C-141...Not sure as to what instructions you are needing from the BLM...? A reputable environmental company will be able to assist you with this clean-up and proper procedures.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist
Bureau of Land Management

620 E. Greene St
Carlsbad, NM 88220

575.234.5905 - Direct
575.361.0084 - Cellular

stucker@blm.gov



On Mon, Oct 5, 2015 at 4:31 PM, Heather Dolphin <heather.dolphin@memorialrd.com> wrote:

Please find attached the C-141 for the spill at the Loco Hills #2.

Please note I had the location name incorrect below.

Heather Dolphin

Sr. Regulatory Specialist
Memorial Resource Development Corp.
500 Dallas Street, Suite 1800
Houston , TX 77002
Direct (832) 408-8603
Mobile (832)-797-1334
Main (713) 588-8300
Fax (713) 588-8301
heather.dolphin@memorialrd.com

[Click here for Memorial Resource Development's Electronic Mail Disclaimer](#)

From: Arias, Arthur [mailto:aaarias@blm.gov]
Sent: Monday, September 28, 2015 8:16 AM
To: Heather Dolphin <heather.dolphin@memorialrd.com>
Subject: Re: Memorial Burnham Battery Spill

Thank you,, also all spills can go directly to stucker@blm.gov she is the primary contact for spills in our office but they can b e-mail to me as well. thanks for keep us updated....

Arthur Arias

aaarias@blm.gov

Environmental Protection Specialist
Bureau Of Land Management, Carlsbad Field Office
575-234-6230 Cell 575-499-3378

On Fri, Sep 25, 2015 at 7:36 PM, Heather Dolphin <heather.dolphin@memorialrd.com> wrote:

Memorial had a hole in the injection line coming from the Burnham Battery to the KLM well. Approx 10bbls PW spilled in the pasture, about 90yards x 2' soaked into the sand immediately. I will follow-up with a C-141 on Monday.

Heather Dolphin
Sr. Regulatory Specialist
Memorial Resource Development Corp.
500 Dallas Street, Suite 1800
Houston, TX 77002
Direct (832) 408-8603
Mobile (832)-797-1334
Main (713) 588-8300
Fax (713) 588-8301
heather.dolphin@memorialrd.com

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 381834

CONDITIONS

Operator: MEMORIAL PRODUCTION OPERATING, LLC 1301 Mckinney Suite 2100 Houston, TX 77010	OGRID: 303900
	Action Number: 381834
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
amaxwell	Historical document upload.	9/9/2024