

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 383774

QUESTIONS

Operator: Murchison Oil and Gas, LLC 7250 Dallas Parkway Plano, TX 75024	OGRID:
	15363
	Action Number:
	383774
Action Type:	
[NOTIFY] Notification Of Liner Inspection (C-141L)	

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2415757870
Incident Name	NAPP2415757870 CARBON VALLEY 31 FEDERAL COM #001H @ 30-015-37603
Incident Type	Other
Incident Status	Initial C-141 Approved
Incident Well	[30-015-37603] CARBON VALLEY 31 FEDERAL COM #001H

Location of Release Source

Site Name	CARBON VALLEY 31 FEDERAL COM #001H
Date Release Discovered	04/10/2024
Surface Owner	Federal

Liner Inspection Event Information*Please answer all the questions in this group.*

What is the liner inspection surface area in square feet	5,300
Have all the impacted materials been removed from the liner	Yes
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	09/19/2024
Time liner inspection will commence	10:00 AM
Please provide any information necessary for observers to liner inspection	Please contact dimitry@mcnabbpartners.com if needed. 917-497-6890
Please provide any information necessary for navigation to liner inspection site	GPS coordinates: 32.8762606, -104.207663

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 383774

CONDITIONS

Operator: Murchison Oil and Gas, LLC 7250 Dallas Parkway Plano, TX 75024	OGRID: 15363
	Action Number: 383774
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
aparkermp	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	9/16/2024