

### SITE INFORMATION

Closure Report
Blue Steel 21 Fed Com TB
Incident #: NAPP2419756826
Eddy County, New Mexico
Unit A Sec 28 T23S R29E
32.2797505°, -103.9840404°

Produced Water Release
Point of Release: Equipment Failure
Release Date: 07/15/2024

Volume Released: 180 barrels of Produced Water Volume Recovered: 180 barrels of Produced Water

# CARMONA RESOURCES



Prepared for: Marathon Oil Corporation 990 Town and Country Blvd, Houston, Texas 77024

Prepared by: Carmona Resources, LLC 310 West Wall Street Suite 500 Midland, Texas 79701



### TABLE OF CONTENTS

1.0 SITE INFORMATION AND BACKGROUND

2.0 SITE CHARACTERIZATION AND GROUNDWATER

3.0 NMAC REGULATORY CRITERIA

4.0 LINER INSPECTION ACTIVITIES

**5.0 CONCLUSIONS** 

### **FIGURES**

FIGURE 1 OVERVIEW FIGURE 2 TOPOGRAPHIC

FIGURE 3 SECONDARY CONTAINMENT MAP

### **APPENDICES**

APPENDIX A PHOTOS

APPENDIX B N.O.R. / INITIAL C-141 / LINER INSPECTION NOTIFICATION

APPENDIX C SITE CHARACTERIZATION AND GROUNDWATER



August 19, 2024

Mike Bratcher District Supervisor Oil Conservation Division, District 2 811 S. First Street Artesia, New Mexico 88210

**Re:** Closure Report

Blue Steel 21 Fed Com TB Marathon Oil Corporation Incident ID: NAPP2419756826

Site Location: Unit A, S28, T23S, R29E (Lat 32.2797505°, Long -103.9840404°)

**Eddy County, New Mexico** 

Mr. Bratcher:

On behalf of Marathon Oil Corporation (Marathon), Carmona Resources, LLC has prepared this letter to document site activities for the Blue Steel 21 Fed Com TB. The site is located at 32.2797505°, -103.9840404° within Unit A, S28, T23S, R29E, in Eddy County, New Mexico (Figures 1 and 2).

### 1.0 Site Information and Background

Based on the initial C-141 obtained from the New Mexico Oil Conservation Division (NMOCD), the release was discovered on July 15, 2024, caused by a pinhole developing on a tank collar. It resulted in the release of approximately one hundred eighty (180) barrels of produced water inside the lined facility, and approximately one hundred eighty (180) barrels of produced water were recovered within the lined facility. See Figure 3. The initial C-141 form is attached in Appendix B.

### 2.0 Site Characterization and Groundwater

The site is located within a medium karst area. Based on a review of the New Mexico Office of State Engineers and USGS databases, there is one known water source within a 0.50-mile radius of the location. The closest well is located approximately 0.10 miles northwest of the site in S28, T23S, R29E and was drilled in 2000. The well has a reported depth to groundwater of 18.0 feet below the ground surface (ft bgs). A copy of the associated point of diversion is attached in Appendix C.

### 3.0 NMAC Regulatory Criteria

Per the NMOCD regulatory criteria established in 19.15.29.12 NMAC, the following criteria were utilized in assessing the site.

- Benzene: 10 milligrams per kilogram (mg/kg).
- Benzene, toluene, ethylbenzene, and total xylenes (BTEX): 50 mg/kg.
- TPH: 100 mg/kg (GRO + DRO + MRO).
- Chloride: 600 mg/kg.



### 4.0 Liner Inspection Activities/Site Assessment Activities

On August 6, 2024, Carmona Resources, LLC conducted liner inspection activities to assess the liner's integrity within the facility. Before performing the liner inspection, the NMOCD division office was notified via NMOCD web portal on August 2, 2024, per Subsection D of 19.15.29.12 NMAC. See Appendix C. Carmona Resources, LLC personnel inspected the liner visually and determined it to be intact with no integrity issues.

Refer to the Photolog attached in Appendix A.

### 5.0 Conclusions

Based on the liner inspection throughout the facility, no further actions are required at the site. The final C-141 is attached, and Marathon formally requests the closure of the spill. If you have any questions regarding this report or need additional information, please contact us at 432-813-9044.

Sincerely,

Carmona Resources, LLC

Clinton Merritt

**Environmental Manager** 

Devin Dominguez Sr. Project Manager

# **FIGURES**


# CARMONA RESOURCES




MARATHON OIL CORPORATION BLUE STEEL 21 FED COM TB EDDY COUNTY, NEW MEXICO 32.2797505°, -103.9840404°

CARMONA RESOURCES

FIGURE 1





## **APPENDIX A**

# CARMONA RESOURCES

### PHOTOGRAPHIC LOG

### **Marathon Oil Corporation**

### Photograph No. 1

Facility: Blue Steel 21 Fed Com TB

County: Eddy County, New Mexico

**Description:** 

View Southeast, area of facility sign.



### Photograph No. 2

Facility: Blue Steel 21 Fed Com TB

County: Eddy County, New Mexico

**Description:** 

View Southeast area of lined facility.



### Photograph No. 3

Facility: Blue Steel 21 Fed Com TB

County: Eddy County, New Mexico

**Description:** 

View Southeast, area of lined facility.



### PHOTOGRAPHIC LOG

### **Marathon Oil Corporation**

### Photograph No. 4

Facility: Blue Steel 21 Fed Com TB

County: Eddy County, New Mexico

**Description:** 

View North, area of lined facility.



### Photograph No. 5

Facility: Blue Steel 21 Fed Com TB

County: Eddy County, New Mexico

**Description:** 

View North, area of lined facility.



### Photograph No. 6

Facility: Blue Steel 21 Fed Com TB

County: Eddy County, New Mexico

**Description:** 

View West, area of lined facility.



### PHOTOGRAPHIC LOG

### **Marathon Oil Corporation**

Photograph No. 7

Facility: Blue Steel 21 Fed Com TB

County: Eddy County, New Mexico

**Description:** 

View Southeast, area of lined facility.



Photograph No. 8

Facility: Blue Steel 21 Fed Com TB

County: Eddy County, New Mexico

**Description:** 

View Southeast, area of lined facility.



Photograph No. 9

Facility: Blue Steel 21 Fed Com TB

County: Eddy County, New Mexico

**Description:** 

View North, area of lined facility.



## **APPENDIX B**

# CARMONA RESOURCES

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

### **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 364194

### **QUESTIONS**

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
990 Town & Country Blvd.	Action Number:
Houston, TX 77024	364194
	Action Type:
	[NOTIFY] Notification Of Release (NOR)

### QUESTIONS

Location of Release Source	
Please answer all the questions in this group.	
Site Name	BLUE STEEL 21 FED COM TB
Date Release Discovered	07/15/2024
Surface Owner	Federal

ncident Details	
Please answer all the questions in this group.	
Incident Type	Produced Water Release
Did this release result in a fire or is the result of a fire	No
Did this release result in any injuries	No
Has this release reached or does it have a reasonable probability of reaching a watercourse	No
Has this release endangered or does it have a reasonable probability of endangering public health	No
Has this release substantially damaged or will it substantially damage property or the environment	No
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No

Nature and Volume of Release		
Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.		
Crude Oil Released (bbls) Details	Not answered.	
Produced Water Released (bbls) Details	Cause: Equipment Failure   Production Tank   Produced Water   Released: 167 BBL   Recovered: 0 BBL   Lost: 167 BBL.	
Is the concentration of chloride in the produced water >10,000 mg/l	Yes	
Condensate Released (bbls) Details	Not answered.	
Natural Gas Vented (Mcf) Details	Not answered.	
Natural Gas Flared (Mcf) Details	Not answered.	
Other Released Details	Not answered.	
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Release occurred due to a pin hole developing on a tank collar. The release remained inside lined containment and vac trucks are called out to assist in the recovery of the fluids.	

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

### **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 364194

QUESTIONS	(continued)

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
990 Town & Country Blvd.	Action Number:
Houston, TX 77024	364194
l l	Action Type:
	[NOTIFY] Notification Of Release (NOR)

### QUESTIONS

Nature and Volume of Release (continued)		
Is this a gas only submission (i.e. only significant Mcf values reported)	No, according to supplied volumes this does not appear to be a "gas only" report.	
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	Yes	
Reasons why this would be considered a submission for a notification of a major release	From paragraph A. "Major release" determine using: (1) an unauthorized release of a volume, excluding gases, of 25 barrels or more.	
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e. gas only) are to be submitted on the C-129 form.		

Initial Response		
The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury.		
The source of the release has been stopped	True	
The impacted area has been secured to protect human health and the environment	True	
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True	
All free liquids and recoverable materials have been removed and managed appropriately	True	
If all the actions described above have not been undertaken, explain why	Not answered.	

Per Paragraph 4 of Subsection B of 19.15.29.8 NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of actions to date in the follow-up C-141 submission. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please prepare and attach all information needed for closure evaluation in the follow-up C-141 submission.

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

### **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 364194

### **ACKNOWLEDGMENTS**

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
990 Town & Country Blvd.	Action Number:
Houston, TX 77024	364194
	Action Type:
	[NOTIFY] Notification Of Release (NOR)

### **ACKNOWLEDGMENTS**

V	I acknowledge that I am authorized to submit notification of a release on behalf of my operator.
V	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to my operator) to track the notification(s) and corrective action(s) for a release, pursuant to NMAC 19.15.29.
V	I acknowledge that creating a new incident file will require my operator to file subsequent submission(s) of form "C-141, Application for administrative approval of a release notification and corrective action", pursuant to NMAC 19.15.29.
V	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment.
V	I acknowledge the fact that the acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment.
V	I acknowledge the fact that, in addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 364194

### **CONDITIONS**

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
990 Town & Country Blvd.	Action Number:
Houston, TX 77024	364194
	Action Type:
	[NOTIFY] Notification Of Release (NOR)

### CONDITIONS

Created	Condition	Condition
Ву		Date
icastro	When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-141.	7/15/2024

### **MRO Spill Calculation Tool**

Standing Liquid Inputs:							
		Width (ft.) (Area					
		for	Avg. Liquid		Total Volume	Water Volume	Oil Volume
<del>-</del>	Length (ft.)	Displacement)	Depth (in.)	% Oil	(bbls)	(bbls)	(bbls)
Rectangle Area #1					0.00	0.00	0.00
Rectangle Area #2					0.00	0.00	0.00
Rectangle Area #3					0.00	0.00	0.00
Rectangle Area #4					0.00	0.00	0.00
Rectangle Area #5					0.00	0.00	0.00
Rectangle Area #6					0.00	0.00	0.00
Vessel Displacement					0.00	0.00	0.00
Vessel Displacement					0.00	0.00	0.00
_			V	ac truck recovery:	180.00	0.00	0.00
				•			
Saturated Soil Inputs:		Soil Type: Width (ft.) /	Gravel Loam Avg. Saturated	]	Total Volume	Water Volume	Oil Volume
	Length (ft.)	(SQ Ft)	Depth (in.)	% Oil	(bbls)	(bbls)	(bbls)
Rectangle Area #1					0.00	0.00	0.00
Rectangle Area #2					0.00	0.00	0.00
Rectangle Area #3					0.00	0.00	0.00
Rectangle Area #4					0.00	0.00	0.00
Rectangle Area #5					0.00	0.00	0.00
Rectangle Area #6					0.00	0.00	0.00
SQ FT Calc					0.00	0.00	0.00
Rectangle Area #8					0.00	0.00	0.00
		•		Saturated Volume	0.00	0.00	0.00
				ı		-	
					<b>Total Volume</b>	Water Volume	Oil Volume
					(bbls)	(bbls)	(bbls)
			Total Sp	oill Volume (bbls):	180.00	0.00	0.00
				pill Volume (gals):	7560.00	0.00	0.00
omments:							
omments.							
			Color Key:	Required Input	Supplemental	No Input	
			color key.	Cells	Input Cells	(Calculations)	No Input
				cens	input cens	(calculations)	
		Gro	und/Vegetatio	n Overcarav			
`			Approximate D				
Cover Type Ground		Microns	Approximate D	epin (in)			
Oull Color		10	0.00003281				
Dark Color			0.00016404				

FROM



204 Kennel Ln. Carlsbad, NM 88220 (575) 725-8802

HOURS

TO

Released to Imaging: 10/30/2024 2:50:04 PM STER BASE MUD

TIME TICKET

Nº 31176

CONTRACTOR SIGNATURE

DATE TAND	5-24		
CUSTOMER AVOLT	non C	1	
WORK LOCATION (		- 0	
Phe	steel	Foed !	CTF

DESCRIPTION

Drive From yard to

	Cleaning Houled on the conte	the co	of P	
NAME	BARRELS/YDS	UNIT: NO.	48 HOURS	AMOUNT
Pacheco	90	766		
SERVICE PROVIDE	FRESH WATER	TOTAL HO	URS	
VAC TRUCK WINCH TRUCK JET PUMP	BRINE WATER PRODUCED WATER  DIL BASE MUD	CUSTON	IER SIGNATI	JRE



204 Kennel Ln. Carlsbad, NM 88220 (575) 725-8802 TIME TICKET

Nº 28298

CUSTOMER NAVATION OIL RIG NAME / NUMBER

WORK LOCATION (NAME)
BLUE STEEL FED CTB

			HAULED 1 LOAD			
			OF PLW TO	DEPO	SAL	
				- January 19 30 1931	Total Manager	70.00
	NAME		BARRELS/YDS	UNIT. NO.	HOURS	AMO
		1				
DER	no C	ANEL	A			
24900 ESCHEROLES (A	of Other Assessed	SERVICE PR	OVIDED	TOTAL HO	URS	1975

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

### **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 365229

### **QUESTIONS**

ı	Operator:	OGRID:
ı	MARATHON OIL PERMIAN LLC	372098
ı	990 Town & Country Blvd.	Action Number:
ı	Houston, TX 77024	365229
ı		Action Type:
ı		[C-141] Initial C-141 (C-141-v-Initial)

### QUESTIONS

Prerequisites		
Incident ID (n#)	nAPP2419756826	
Incident Name	NAPP2419756826 BLUE STEEL 21 FED COM TB @ 0	
Incident Type	Produced Water Release	
Incident Status	Initial C-141 Received	
Incident Facility	[fAPP2126035874] BLUE STEEL 21 FED COM TB	

Location of Release Source		
Please answer all the questions in this group.		
Site Name	BLUE STEEL 21 FED COM TB	
Date Release Discovered	07/15/2024	
Surface Owner	Federal	

Incident Details		
Please answer all the questions in this group.		
Incident Type	Produced Water Release	
Did this release result in a fire or is the result of a fire	No	
Did this release result in any injuries	No	
Has this release reached or does it have a reasonable probability of reaching a watercourse	No	
Has this release endangered or does it have a reasonable probability of endangering public health	No	
Has this release substantially damaged or will it substantially damage property or the environment	No	
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No	

Nature and Volume of Release	
faterial(s) released, please answer all that apply below. Any calculations or specific justifications	for the volumes provided should be attached to the follow-up C-141 submission.
Crude Oil Released (bbls) Details	Not answered.
Produced Water Released (bbls) Details	Cause: Equipment Failure   Production Tank   Produced Water   Released: 180 BBL   Recovered: 180 BBL   Lost: 0 BBL.
Is the concentration of chloride in the produced water >10,000 mg/l	Yes
Condensate Released (bbls) Details	Not answered.
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Not answered.
Other Released Details	Not answered.
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Release occurred due to a pin hole developing on a tank collar. The release remained insid lined containment, fluids were recovered, and liner pressure washed.

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

### **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 365229

Phone:(505) 476-3470 Fax:(505) 476-3462	
QUES	STIONS (continued)
Operator:	OGRID:
MARATHON OIL PERMIAN LLC 990 Town & Country Blvd.	372098
Houston, TX 77024	Action Number: 365229
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)
QUESTIONS	•
Nature and Volume of Release (continued)	
Is this a gas only submission (i.e. only significant Mcf values reported)	No, according to supplied volumes this does not appear to be a "gas only" report.
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	Yes
Reasons why this would be considered a submission for a notification of a major release	From paragraph A. "Major release" determine using:  (1) an unauthorized release of a volume, excluding gases, of 25 barrels or more.
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas	s (i.e. gas only) are to be submitted on the C-129 form.
F =	
Initial Response	
The responsible party must undertake the following actions immediately unless they could create	a safety hazard that would result in injury.
The source of the release has been stopped	True
The impacted area has been secured to protect human health and the environment	True
Released materials have been contained via the use of berms or dikes, absorber pads, or other containment devices	True
All free liquids and recoverable materials have been removed and managed appropriately	True
If all the actions described above have not been undertaken, explain why	Not answered.
	nediation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of pleted or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of re evaluation in the follow-up C-141 submission.
to report and/or file certain release notifications and perform corrective actions for rethe OCD does not relieve the operator of liability should their operations have failed	ny knowledge and understand that pursuant to OCD rules and regulations all operators are required eleases which may endanger public health or the environment. The acceptance of a C-141 report by to adequately investigate and remediate contamination that pose a threat to groundwater, surface port does not relieve the operator of responsibility for compliance with any other federal, state, or
I hereby agree and sign off to the above statement	Name: Isaac Castro Email: icastro@marathonoil.com Date: 07/18/2024

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

### **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 3

Action 365229

**QUESTIONS** (continued)

Opera	ator:	OGRID:
	MARATHON OIL PERMIAN LLC	372098
	990 Town & Country Blvd.	Action Number:
	Houston, TX 77024	365229
		Action Type:
		[C-141] Initial C-141 (C-141-v-Initial)

### QUESTIONS

Site Characterization				
Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date.				
What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs)	Not answered.			
What method was used to determine the depth to ground water	Not answered.			
Did this release impact groundwater or surface water	Not answered.			
What is the minimum distance, between the closest lateral extents of the release and the following surface areas:				
A continuously flowing watercourse or any other significant watercourse	Not answered.			
Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	Not answered.			
An occupied permanent residence, school, hospital, institution, or church	Not answered.			
A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes	Not answered.			
Any other fresh water well or spring	Not answered.			
Incorporated municipal boundaries or a defined municipal fresh water well field	Not answered.			
A wetland	Not answered.			
A subsurface mine	Not answered.			
An (non-karst) unstable area	Not answered.			
Categorize the risk of this well / site being in a karst geology	Not answered.			
A 100-year floodplain	Not answered.			
Did the release impact areas not on an exploration, development, production, or storage site	Not answered.			

Remediation Plan					
Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.					
Requesting a remediation plan approval with this submission	No				
The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.					

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 365229

### **CONDITIONS**

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
990 Town & Country Blvd.	Action Number:
Houston, TX 77024	365229
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

### CONDITIONS

Created By		Condition Date
nvelez	None	7/18/2024

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

QUESTIONS

Action 365170

### **QUESTIONS**

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
990 Town & Country Blvd.	Action Number:
Houston, TX 77024	365170
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

### QUESTIONS

Prerequisites						
Incident ID (n#)	nAPP2419756826					
Incident Name	NAPP2419756826 BLUE STEEL 21 FED COM TB @ 0					
Incident Type	Produced Water Release					
Incident Status	Notification Accepted					
Incident Facility	[fAPP2126035874] BLUE STEEL 21 FED COM TB					

Location of Release Source				
Site Name	BLUE STEEL 21 FED COM TB			
Date Release Discovered	07/15/2024			
Surface Owner	Federal			

Liner Inspection Event Information							
Please answer all the questions in this group.							
What is the liner inspection surface area in square feet	33,184						
Have all the impacted materials been removed from the liner	Yes						
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	08/06/2024						
Time liner inspection will commence	09:00 AM						
Please provide any information necessary for observers to liner inspection	Clinton Merritt 432-813-9044						
Please provide any information necessary for navigation to liner inspection site	From the intersection of CR 741 and CR 742, travel east on CR 742 for 1.81 miles. Turn south onto unmarked lease road andtravel for 1.83 miles. Battery is on the south side of the lease road.						

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 365170

### CONDITIONS

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
•	Action Number:
Houston, TX 77024	365170
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

### CONDITIONS

Created By	Condition	Condition Date
cswansonsteege	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	8/2/2024

## **APPENDIX C**

# CARMONA RESOURCES







# New Mexico Office of the State Engineer Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.) (R=POD has been replaced, O=orphaned, C=the file is

closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest) (NAD83 UTM in meters)

(In feet)

	POD Sub-		QC	Q Q							Depth	Depth	Water
POD Number	Code basin	County	64 1	6 4	Sec	Tws	Rng	Х	Υ	Distance	•	•	Column
<u>C 02707</u>	С	ED		2	28	23S	29E	595535	3571868* 🌍	140	40	18	22
C 01627	С	ED	1 4	1 4	28	23S	29E	595649	3570959* 🌕	938	170		
<u>C 02721</u>	CUB	ED	2	2 3	21	23S	29E	594915	3572879* 🌕	1239	150		
C 02797	CUB	ED	2	2 3	22	23S	29E	596540	3572895* 🌕	1322	200		
C 02613	CUB	ED	4 4	1 2	20	23S	29E	594203	3573176* 🌑	1947	400		
C 02720	CUB	ED	2	2 1	21	23S	29E	594911	3573690*	1947	150		
C 03057 EXPLORE	CUB	ED	4 ′	1 1	21	23S	29E	594605	3573586* 🎒	1997	150		

Average Depth to Water:

18 feet

Minimum Depth:

18 feet

Maximum Depth:

18 feet

**Record Count: 7** 

UTMNAD83 Radius Search (in meters):

Easting (X): 595672 Northing (Y): 3571897 Radius: 2000

\*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.



## New Mexico Office of the State Engineer

# **Point of Diversion Summary**

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest)

(NAD83 UTM in meters)

Well Tag **POD Number**  Q64 Q16 Q4 Sec Tws Rng

 $\mathbf{X}$ 

C 02707

23S

595535 3571868\*

**Driller License:** 

1348

**Driller Company:** 

TAYLOR WATER WELL SERVICE

**Driller Name:** 

**Drill Start Date:** 06/09/2000 **Drill Finish Date:** 

06/09/2000

29E

Plug Date:

Log File Date:

08/28/2000

**PCW Rcv Date:** 

Source:

Shallow

**Pump Type:** 

Pipe Discharge Size:

**Estimated Yield:** Depth Water:

700 GPM

**Casing Size:** 

2.38

**Depth Well:** 

40 feet

18 feet

Water Bearing Stratifications:

**Bottom Description** Top 36

78 Limestone/Dolomite/Chalk

**Casing Perforations:** 

**Bottom** Top 35

40


The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

10/18/23 12:53 PM

POINT OF DIVERSION SUMMARY

<sup>\*</sup>UTM location was derived from PLSS - see Help

### **FEMA National Flood Hazard Layer (NFHL)**



Bureau of Land Management, Texas Parks & Wildlife, Esri, HERE, Garmin, INCREMENT P, USGS, METI/NASA, EPA, USDA


### **FEMA National Flood Hazard Layer (NFHL) NFHL** Salt Lahe Flood Hazard Zones 1% Annual Chance Flood Hazard Regulatory Floodway Zone A Special Floodway Area of Undetermined Flood Hazard 0.2% Annual Chance Flood Hazard Future Conditions 1% Annual Chance Flood Hazard Area with Reduced Risk Due to Levee Area with Risk Due to Levee

FEMA flood layer 0.3mi

Maxar | Esri Community Maps Contributors, New Mexico State University, Texas Parks & Wildlife, © OpenStreetMap, Microsoft, CONANP, Esri, TomTom, Garmin, SafeGraph, GeoTechnologies, Inc, METI/NASA, USGS, EPA, NPS, US Census Bureau, USDA, USFWS


esri

# BLUE STEEL 21 FED COM TB (05.19.2024)



OSW Water Bodys

OSE Streams



Esri, NASA, NGA, USGS, FEMA, Esri Community Maps Contributors, New Mexico State University, Texas Parks & Wildlife, © OpenStreetMap, Microsoft, CONANP, Esri, TomTom, Garmin, SafeGraph, GeoTechnologies, Inc, METI/NASA, USGS, EPA, NPS, US Census Bureau,

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

### **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 377722

### **QUESTIONS**

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
990 Town & Country Blvd.	Action Number:
Houston, TX 77024	377722
	Action Type:
	[C-141] Remediation Closure Request C-141 (C-141-v-Closure)

### QUESTIONS

Prerequisites						
Incident ID (n#)	nAPP2419756826					
Incident Name	NAPP2419756826 BLUE STEEL 21 FED COM TB @ 0					
Incident Type	Produced Water Release					
Incident Status	Remediation Closure Report Received					
Incident Facility	[fAPP2126035874] BLUE STEEL 21 FED COM TB					

Location of Release Source	
Please answer all the questions in this group.	
Site Name	BLUE STEEL 21 FED COM TB
Date Release Discovered	07/15/2024
Surface Owner	Federal

Incident Details	
Please answer all the questions in this group.	
Incident Type	Produced Water Release
Did this release result in a fire or is the result of a fire	No
Did this release result in any injuries	No
Has this release reached or does it have a reasonable probability of reaching a watercourse	No
Has this release endangered or does it have a reasonable probability of endangering public health	No
Has this release substantially damaged or will it substantially damage property or the environment	No
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No

Nature and Volume of Release	
Material(s) released, please answer all that apply below. Any calculations or specific justifications is	for the volumes provided should be attached to the follow-up C-141 submission.
Crude Oil Released (bbls) Details	Not answered.
Produced Water Released (bbls) Details	Cause: Equipment Failure   Production Tank   Produced Water   Released: 180 BBL   Recovered: 180 BBL   Lost: 0 BBL.
Is the concentration of chloride in the produced water >10,000 mg/l	Yes
Condensate Released (bbls) Details	Not answered.
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Not answered.
Other Released Details	Not answered.
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Release occurred due to a pin hole developing on a tank collar. The release remained insid lined containment, fluids were recovered, and liner pressure washed.

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe. NM 87505

QUESTIONS, Page 2

Action 377722

Phone:(505) 476-3470 Fax:(505) 476-3462	
QUESTI	IONS (continued)
Operator:  MARATHON OIL PERMIAN LLC 990 Town & Country Blvd.	OGRID: 372098 Action Number:
Houston, TX 77024	377722  Action Type:  [C-141] Remediation Closure Request C-141 (C-141-v-Closure)
QUESTIONS	
Nature and Volume of Release (continued)	
Is this a gas only submission (i.e. only significant Mcf values reported)	No, according to supplied volumes this does not appear to be a "gas only" report.
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	Yes
Reasons why this would be considered a submission for a notification of a major release	From paragraph A. "Major release" determine using: (1) an unauthorized release of a volume, excluding gases, of 25 barrels or more.
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e.	e. gas only) are to be submitted on the C-129 form.
Initial Response	
The responsible party must undertake the following actions immediately unless they could create a s	safety hazard that would result in injury.
The source of the release has been stopped	True
The impacted area has been secured to protect human health and the environment	True
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True
All free liquids and recoverable materials have been removed and managed appropriately	True
If all the actions described above have not been undertaken, explain why	Not answered.
	i lation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of ted or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of evaluation in the follow-up C-141 submission.
to report and/or file certain release notifications and perform corrective actions for releate the OCD does not relieve the operator of liability should their operations have failed to	knowledge and understand that pursuant to OCD rules and regulations all operators are required asses which may endanger public health or the environment. The acceptance of a C-141 report by adequately investigate and remediate contamination that pose a threat to groundwater, surface t does not relieve the operator of responsibility for compliance with any other federal, state, or

Name: Cody Swanson Steege Title: Compliance Supervisor

Date: 08/29/2024

Email: swansonste@marathonoil.com

I hereby agree and sign off to the above statement

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

QUESTIONS, Page 3

Action 377722

### **QUESTIONS** (continued)

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
990 Town & Country Blvd.	Action Number:
Houston, TX 77024	377722
	Action Type:
	[C-141] Remediation Closure Request C-141 (C-141-v-Closure)

### QUESTIONS

Site Characterization	
Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date.	
What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs)	Less than or equal 25 (ft.)
What method was used to determine the depth to ground water	NM OSE iWaters Database Search
Did this release impact groundwater or surface water	No
What is the minimum distance, between the closest lateral extents of the release and the following surface areas:	
A continuously flowing watercourse or any other significant watercourse	Between 1000 (ft.) and ½ (mi.)
Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	Between 1000 (ft.) and ½ (mi.)
An occupied permanent residence, school, hospital, institution, or church	Greater than 5 (mi.)
A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes	Greater than 5 (mi.)
Any other fresh water well or spring	Greater than 5 (mi.)
Incorporated municipal boundaries or a defined municipal fresh water well field	Greater than 5 (mi.)
A wetland	Between 1000 (ft.) and ½ (mi.)
A subsurface mine	Greater than 5 (mi.)
An (non-karst) unstable area	Greater than 5 (mi.)
Categorize the risk of this well / site being in a karst geology	Medium
A 100-year floodplain	Between 1000 (ft.) and ½ (mi.)
Did the release impact areas not on an exploration, development, production, or storage site	No

Remediation Plan		
Please answer all the questions that apply or are indicated. This information must be provided to	the appropriate district office no later than 90 days after the release discovery date.	
Requesting a remediation plan approval with this submission	Yes	
Attach a comprehensive report demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined, pursuant to 19.15.29.11 NMAC and 19.15.29.13 NMAC.		
Have the lateral and vertical extents of contamination been fully delineated	Yes	
Was this release entirely contained within a lined containment area	Yes	
Per Subsection B of 19.15.29.11 NMAC unless the site characterization report includes completed efforts at remediation, the report must include a proposed remediation plan in accordance with 19.15.29.12 NMAC, which includes the anticipated timelines for beginning and completing the remediation.		
On what estimated date will the remediation commence	08/06/2024	
On what date will (or did) the final sampling or liner inspection occur	08/06/2024	
On what date will (or was) the remediation complete(d)	08/06/2024	
What is the estimated surface area (in square feet) that will be remediated	0	
What is the estimated volume (in cubic yards) that will be remediated	0	
These estimated dates and measurements are recognized to be the best guess or calculation at the time of submission and may (be) change(d) over time as more remediation efforts are completed.		

The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 **District II** 

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III** 

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 4

Action 377722

### **QUESTIONS** (continued)

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
990 Town & Country Blvd.	Action Number:
Houston, TX 77024	377722
	Action Type:
	[C-141] Remediation Closure Request C-141 (C-141-v-Closure)

### QUESTIONS

Remediation Plan (continued)	
Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.	
This remediation will (or is expected to) utilize the following processes to remediate / reduce contaminants:	
(Select all answers below that apply.)	
Is (or was) there affected material present needing to be removed	Yes
Is (or was) there a power wash of the lined containment area (to be) performed	Yes
OTHER (Non-listed remedial process)	No
Per Subsection B of 19 15 29 11 NMAC unless the site characterization report includes completed efforts at remediation, the report must include a proposed remediation plan in accordance with 19 15 29 12 NMAC.	

Per Subsection B of 19.15.29.11 NMAC unless the site characterization report includes completed efforts at remediation, the report must include a proposed remediation plan in accordance with 19.15.29.12 NMAC which includes the anticipated timelines for beginning and completing the remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Name: Cody Swanson Steege
Title: Compliance Supervisor
Email: swansonste@marathonoil.com

The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.

Date: 08/29/2024

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 **District II** 

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III** 

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 6

Action 377722

QUESTIONS (	(continued)

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
990 Town & Country Blvd.	Action Number:
Houston, TX 77024	377722
	Action Type:
	[C-141] Remediation Closure Request C-141 (C-141-v-Closure)

### QUESTIONS

Liner Inspection Information	
Last liner inspection notification (C-141L) recorded	365170
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	08/06/2024
Was all the impacted materials removed from the liner	Yes
What was the liner inspection surface area in square feet	33184

Remediation Closure Request				
Only answer the questions in this group if seeking remediation closure for this release because all remediation steps have been completed.				
Requesting a remediation closure approval with this submission	Yes			
Have the lateral and vertical extents of contamination been fully delineated	Yes			
Was this release entirely contained within a lined containment area	Yes			
What was the total surface area (in square feet) remediated	0			
What was the total volume (cubic yards) remediated	0			
Summarize any additional remediation activities not included by answers (above)	Based on the liner inspection throughout the facility, no further actions are required at the site. The final C-141 is attached, and Marathon formally requests the closure of the spill.			

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (in .pdf format) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

I hereby agree and sign off to the above statement

Name: Cody Swanson Steege
Title: Compliance Supervisor
Email: swansonste@marathonoil.com
Date: 08/29/2024

Released to Imaging: 10/30/2024 2:50:04 PM

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

### **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 377722

### **CONDITIONS**

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
990 Town & Country Blvd.	Action Number:
Houston, TX 77024	377722
	Action Type:
	[C-141] Remediation Closure Request C-141 (C-141-v-Closure)

### CONDITIONS

Created	Condition	Condition Date
Ву		
nvelez	Liner inspection approved, release resolved.	10/30/2024