Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 412066

QUESTIONS

Operator:	OGRID:
CAZA OPERATING, LLC	249099
200 N Loraine St	Action Number:
Midland, TX 79701	412066
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2218524223
Incident Name	NAPP2218524223 MAD RIVER 13 STATE 3H @ 30-015-43898
Incident Type	Oil Release
Incident Status	Initial C-141 Approved
Incident Well	[30-015-43898] MAD RIVER 13 STATE COM #003H

Location of Release Source	
Site Name	Mad River 13 State 3H
Date Release Discovered	07/02/2022
Surface Owner	State

Liner Inspection Event Information	
Please answer all the questions in this group.	
What is the liner inspection surface area in square feet	14,000
Have all the impacted materials been removed from the liner	Yes
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	12/19/2024
Time liner inspection will commence	10:00 AM
Please provide any information necessary for observers to liner inspection	NTGE - (832) 374-0004
Please provide any information necessary for navigation to liner inspection site	32.211285,-104.135825

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 412066

CONDITIONS

Operator:	OGRID:
CAZA OPERATING, LLC	249099
200 N Loraine St	Action Number:
Midland, TX 79701	412066
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
karrendondo	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	12/16/2024