Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Page 1 of 2

Action 412046

	QUESTIONS
Operator: CAZA OPERATING, LLC	OGRID: 249099
200 N Loraine St Midland, TX 79701	Action Number: 412046
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2302734734
Incident Name	NAPP2302734734 FOREHAND 22 FEDERAL CTB @ 0
Incident Type	Produced Water Release
Incident Status	Initial C-141 Approved

Location of Release Source	
Site Name	Forehand 22 Federal CTB
Date Release Discovered	01/27/2023
Surface Owner	Private

Liner Inspection Event Information

Please answer all the questions in this group.		
What is the liner inspection surface area in square feet	14,000	
Have all the impacted materials been removed from the liner	Yes	
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	12/18/2024	
Time liner inspection will commence	09:00 AM	
Please provide any information necessary for observers to liner inspection	32.289345,-104.170424	
Please provide any information necessary for navigation to liner inspection site	NTGE - (832) 374-0004	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:	1
CAZA OPERATING, LLC	249099	i.
200 N Loraine St	Action Number:	I
Midland, TX 79701	412046	l.
	Action Type:	l.
	[NOTIFY] Notification Of Liner Inspection (C-141L)	

CONDITIONS		
Created By	Condition	Condition Date
karrendondo	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	12/16/2024

Page 2 of 2