Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 412069

QUESTIONS

ı	Operator:	OGRID:
ı	CAZA OPERATING, LLC	249099
ı	200 N Loraine St	Action Number:
ı	Midland, TX 79701	412069
ı		Action Type:
ı		[NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites		
Incident ID (n#)	nAPP2304175781	
Incident Name	NAPP2304175781 MAD RIVER 13 STATE 3-6 CTB @ 0	
Incident Type	Produced Water Release	
Incident Status	Initial C-141 Approved	

Location of Release Source		
Site Name	Mad River 13 State 3-6 CTB	
Date Release Discovered	02/06/2023	
Surface Owner	Private	

Liner Inspection Event Information				
Please answer all the questions in this group.				
What is the liner inspection surface area in square feet	14,000			
Have all the impacted materials been removed from the liner	Yes			
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	12/19/2024			
Time liner inspection will commence	11:00 AM			
Please provide any information necessary for observers to liner inspection	NTGE (832) 374-0004			
Please provide any information necessary for navigation to liner inspection site	32.2117268,-104.1361384			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 412069

CONDITIONS

Operator:	OGRID:
CAZA OPERATING, LLC	249099
200 N Loraine St	Action Number:
Midland, TX 79701	412069
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
karrendondo	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	12/16/2024