

C9+ AnalysisGPA 2172/API 14.5 Report with GPA 2145 Physical Properties

Sample Information

		Sample Information
Sample Name		Blackhawk/Blackcat Compressor
Operator		Permian Resources
Lease		BLACKHAWK/BLAKCAT COMPRESSOR
Sample Date/Time:	Effective Date:	9-30-24 8:00 AM
Sample End Date		
Laboratory		Laboratory Services and Measurement
Technician		LC
Analyzer Type		Gas Chromatograph - TCD
Analyzer Make & Model		Agilent Micro GC 3000
Last Calibration/Validation Date		09-23-2024
Sample Temperature		
Sample Pressure		57 PSI
Sample Flow Rate		
Ambient Temperature		65 F
Heat Tracing		No
Sample Type		Spot
Sampling Method		Fill and Purge
Company Collecting Sample		LSM
Sampled By		DAVID ADAMS
Cylinder #		3516
Mole, Weight, or Percent (For F	lowcal DON'T EDIT)	M
Sample Calculation Method(For	Flowcal DON'T EDIT)	GPA 2172/API 14.5 Report with GPA 2145 Physical Properties
Analysis Date		2024-09-30 14:07:30

Component Results

Component Name	Un-Normalized Mole%	Norm Mole%	
Nitrogen	1.8120	1.8556	
Carbon Dioxide	0.4520	0.4629	
Methane	76.2330	78.0682	
Ethane	12.4580	12.7579	
Propane	2.5170	2.5776	
isobutane	0.8440	0.8643	

Component Name	Un-Normalized Mole%	Norm Mole%
n-Butane	1.8130	1.8566
isopentane	0.4500	0.4608
n-Pentane	0.4080	0.4178
hexanes	0.4100	0.4199
heptanes	0.1810	0.1854
octanes	0.0470	0.0481
nonanes+	0.0240	0.0246
hydrogen sulfide	0.0003	0.0003
Total:	97.6493	100.0000

Results Summary

Result	Dry	Wet/Sat	:
Total Un-Normalized Mole%	97.6493		
Pressure Base (psia)	14.730		
Temperature Base (Deg. F)	60.00		
Gross Heating Value (BTU / Ideal cu.ft.)	1240.7	1219.1	1
Gross Heating Value (BTU / Real cu.ft.)	1245.2	1224.0	0
Relative Density (G), Ideal	0.7275	0.7256	6
Relative Density (G), Real	0.7298	0.7282	2
Compressibility (Z) Factor	0.9965	0.9960	0
Total GPM	19.188	18.962	2

Volumes associated with this C-129 filing are estimations and may be subject to change as data is reconciled. The operator's current practice consists of metering volumes and report in accordance with NMAC 19.15.27.

For inquiries regarding this filing, please contact the operator.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

DEFINITIONS

Action 412097

DEFINITIONS

Operator:	OGRID:
Permian Resources Operating, LLC	372165
300 N. Marienfeld St Ste 1000	Action Number:
Midland, TX 79701	412097
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116

Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 412097

Q	UESTIONS	
Operator:		OGRID:
Permian Resources Operating, LLC 300 N. Marienfeld St Ste 1000		372165 Action Number:
Midland, TX 79701		412097
		Action Type: [C-129] Venting and/or Flaring (C-129)
QUESTIONS		3 (3)
Prerequisites		
Any messages presented in this section, will prevent submission of this application. Please resolve t	these issues before continuing wit	h the rest of the questions.
Incident Well	Unavailable.	
Incident Facility	[fAPP2317036480] BLACK	HAWK/BLACK CAT 16 STATE COM CTB 1
Determination of Reporting Requirements		
Answer all questions that apply. The Reason(s) statements are calculated based on your answers an Was this vent or flare caused by an emergency or malfunction		
Did this vent or flare last eight hours or more cumulatively within any 24-hour	No	
period from a single event	Yes	
Is this considered a submission for a vent or flare event	Yes, minor venting and/or	flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during v	enting and/or flaring that is or may	be a major or minor release under 19.15.29.7 NMAC.
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes	
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No	
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No	
Equipment Involved		
	Not anawarad	
Primary Equipment Involved	Not answered.	
Additional details for Equipment Involved. Please specify	Not answered.	
Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group.		
Methane (CH4) percentage	78	
Nitrogen (N2) percentage, if greater than one percent	2	
Hydrogen Sulfide (H2S) PPM, rounded up	0	
Carbon Dioxide (C02) percentage, if greater than one percent	0	
Oxygen (02) percentage, if greater than one percent	0	
If you are venting and/or flaring because of Bineline Specification, places provide the required appe	ifications for each gas	
If you are venting and/or flaring because of Pipeline Specification, please provide the required specification (CH4) percentage quality requirement	Not answered.	
Nitrogen (N2) percentage quality requirement	Not answered.	
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.	
Carbon Dioxide (C02) percentage quality requirement	Not answered.	
Oxygen (02) percentage quality requirement	Not answered.	

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 2

Action 412097

QUESTI	ONS (continued)		
Operator:	OGRID:		
Permian Resources Operating, LLC 300 N. Marienfeld St Ste 1000	372165 Action Number:		
Midland, TX 79701	412097		
	Action Type: [C-129] Venting and/or Flaring (C-129)		
QUESTIONS			
Date(s) and Time(s)			
Date vent or flare was discovered or commenced	12/06/2024		
Time vent or flare was discovered or commenced	12:00 AM		
Time vent or flare was terminated	11:59 PM		
Cumulative hours during this event	24		
Measured or Estimated Volume of Vented or Flared Natural Gas			
Natural Gas Vented (Mcf) Details	Not answered.		
Natural Gas Flared (Mcf) Details	Cause: Equipment Failure Tank (Any) Natural Gas Flared Released: 122 Mcf Recovered: 0 Mcf Lost: 122 Mcf.		
Other Released Details	Not answered.		
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.		
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.		
Venting or Eleving Regulting from Dougetroom Activity			
Venting or Flaring Resulting from Downstream Activity			
Was this vent or flare a result of downstream activity	No		
Was notification of downstream activity received by this operator	Not answered.		
Downstream OGRID that should have notified this operator	Not answered.		
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare	Not answered.		
Time notined of downstream activity requiring this vent of hare	Not answered.		
Steps and Actions to Prevent Waste			
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True		
Please explain reason for why this event was beyond this operator's control	VRU failing due to contamination of cooler lubricant by triazine		
Steps taken to limit the duration and magnitude of vent or flare	Open valves to divert gas to a second midstream company to relive pressure off the line		
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Clear consistent communication with midstream provider		

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 412097

ACKNOWLEDGMENTS

	Operator:	OGRID:
ı	Permian Resources Operating, LLC	372165
	300 N. Marienfeld St Ste 1000	Action Number:
ı	Midland, TX 79701	412097
ı		Action Type:
		[C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

V	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
V	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
V	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
V	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
V	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 412097

CONDITIONS

Operator:	OGRID:
Permian Resources Operating, LLC	372165
300 N. Marienfeld St Ste 1000	Action Number:
Midland, TX 79701	412097
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
cmevans	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	12/16/2024