

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 413862

QUESTIONS

| | |
|---|--|
| Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102 | OGRID: 6137 |
| | Action Number: 413862 |
| | Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L) |

QUESTIONS

| | |
|-------------------|--|
| Prerequisites | |
| Incident ID (n#) | nAPP2317023604 |
| Incident Name | NAPP2317023604 MEAN GREEN 23 CTB 2 @ 0 |
| Incident Type | Produced Water Release |
| Incident Status | Initial C-141 Approved |
| Incident Facility | [fAPP2123648161] MEAN GREEN 23 CTB 2 |

| | |
|----------------------------|---------------------|
| Location of Release Source | |
| Site Name | MEAN GREEN 23 CTB 2 |
| Date Release Discovered | 06/18/2023 |
| Surface Owner | Federal |

| | |
|---|--|
| Liner Inspection Event Information | |
| Please answer all the questions in this group. | |
| What is the liner inspection surface area in square feet | 7,222 |
| Have all the impacted materials been removed from the liner | Yes |
| Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC | 12/23/2024 |
| Time liner inspection will commence | 08:00 AM |
| Please provide any information necessary for observers to liner inspection | Andrew Franco 806-200-0054 |
| Please provide any information necessary for navigation to liner inspection site | From the intersection of NM 128 and County Rd 2, Travel southwest on County Rd 2 for 11.56 miles, turn East on Anthony Rd for 8.55 miles, turn south on lease Rd for 2.40 miles, turn east on Lease Rd for 1.95 miles, turn north for 0.09 of a mile arriving to location on the right |

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 413862

CONDITIONS

| | |
|---|--|
| Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102 | OGRID: 6137 |
| | Action Number: 413862 |
| | Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L) |

CONDITIONS

| Created By | Condition | Condition Date |
|------------|--|----------------|
| jralej | Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted. | 12/19/2024 |