Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 420939

| QUESTIONS | | | | |
|----------------------------------------------------------------------------------------------------------|------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| Operator: J R OIL, LTD. CO. P.O. Box 53657 Lubbock, TX 79453 | | OGRID: 256073 Action Number: 420939 Action Type: | | |
| QUESTIONS | | [NOTIFY] Notification Of Liner Inspection (C-141L) | | |
| Prerequisites | | | | |
| | 0111000000000000 | | | |
| Incident ID (n#) | nCH1835251206 | | | |
| Incident Name | NCH1835251206 STATE P CTB @ 30-025-12180 | | | |
| Incident Type | Produced Water Release | | | |
| Incident Status | Initial C-141 Appr | Initial C-141 Approved | | |
| Incident Well | [30-025-12180] STATE P #002 | | | |
| Location of Release Source | | | | |
| Site Name | State P CTB | | | |
| Date Release Discovered | 11/12/2018 | | | |
| Surface Owner | Private | | | |
| | | | | |
| Liner Inspection Event Information | | | | |
| Please answer all the questions in this group. What is the liner inspection surface area in square feet | 430 | | | |
| Have all the impacted materials been removed from the liner | Yes | | | |
| Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC | 01/07/2019 | | | |
| Time liner inspection will commence | 09:00 AM | | | |
| Warning: Notification can not be less than two business days prior to conducting liner inspect. | ion. | | | |
| Please provide any information necessary for observers to liner inspection | request associate | pection notification for a legacy release in order to complete the closure of with the incident. A liner inspection was performed at the end of remedial raphic documentation of the liner is included with the closure request. | | |
| Please provide any information necessary for navigation to liner inspection site | No details require | rd for liner inspection that took place in January 2019. | | |

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 420939

CONDITIONS

| Operator: | OGRID: |
|-------------------|----------------------------------------------------|
| J R OIL, LTD. CO. | 256073 |
| P.O. Box 53657 | Action Number: |
| Lubbock, TX 79453 | 420939 |
| | Action Type: |
| | [NOTIFY] Notification Of Liner Inspection (C-141L) |

CONDITIONS

| Created By | | Condition Date |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|
| tetratech | Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted. | 1/15/2025 |