

Napp2510536943 Narrative

4/11/2025 Release

KWU 2309-19K RECYCLING FACILITY fCS1902230487

SAN JUAN COUNTY NEW MEXICO

36.210825 -107.831105

SEC 19, T-23N, R-9W

SURFACE OWNER: BLM

4-11-2025

- A release was reported 4-11-25 at 10:49 a.m. at the Kimbeto Wash Unit 2309-19K water recycling facility. The pump was shut down and crews began damming running water.
- Vacuum trucks were dispatched to begin collection of free fluids from the north side of location running along CR 7800. A berm is placed at the end of the release area to prevent runoff in the event of any precipitation until a work plan is approved by BLM.
- Notifications were sent to required agencies.
- Spill calculated to be 781 bbls of produced water released and 135 bbls recovered. Spill calculation below.

4-14-25

- Investigation findings conclude that this was a result of vandalism.

DEPTH (inches)	LENGTH (feet)	WIDTH (feet)	Effective Porosity	BARRELS (bbls.)	Thickness (feet)
MIST METHOD					
Lt. Mist			NA	0.00000	0.000008
Med. Mist			NA	0.00000	0.00008
Hvy. Mist			NA	0.00000	0.00083
RESIDUAL METHOD (Length X Width X Avg. Depth X Eff. Porosity divided by 5.6146)					
skim				0.00000	0.002604
1/16				0.00000	0.005208
1/8				0.00000	0.010417
1/4				0.00000	0.020803
1/2				0.00000	0.041667
3/4				0.00000	0.062
1				0.00000	0.083333
2				0.00000	0.166666
3				0.00000	0.25
4				0.00000	0.333333
5				0.00000	0.416666
6				0.00000	0.5
7				0.00000	0.583333
8				0.00000	0.666666
9				0.00000	0.75
10				0.00000	0.833333
11				0.00000	0.916666
12	5478	4	0.2	780.53646	1

Soil Type / Effective Porosity

0.25 Gravel - 25% Porosity

0.2 Sand - 20% Porosity

0.15 Clay/Silt/Sand Mix - 15%

0.05 Clay - 5% Porosity

0.03 Caliche - 3%

0.25 Unknown - 25%

*For spills greater than one foot of depth use 12 inches as your depth then multiply the amount of barrels by the number feet of actual depth.

5478'x4'x12"=781bbls

MACRO SECTION

From: [Heather Huntington](#)
To: [Enviro, OCD, EMNRD](#); [Adeloye, Abiodun A](#); [Velez, Nelson, EMNRD](#)
Cc: [Tim Friesenhahn](#); [Melissa Daniels](#)
Subject: Notification of Produced Water Release 3RF-43 KWU 2309-19K RECYCLING FACILITY fCS1902230487 4/11/25
Date: Friday, April 11, 2025 4:37:00 PM

Enduring Resources had a produced water release occur today 4/11/25 at the KWU 2309-19K RECYCLING FACILITY fCS1902230487 located Sec 19 T23N R9W 36.210825 -107.831105. The estimated volume is 781 bbls of produced water and 135 bbls of water was recovered, produced water did leave the location and ran south on CR 7800 in the bar ditch and left the bar ditch in one area. The source of the release was isolated immediately upon discovery and a crew worked to dam up running water. The incident is still being investigated and information is still being gathered at this time, we should have more details on Monday.

Emmanuel-for AFMSS reporting purposes I will use the Kimbeto Wash 771H 30-045-35756.

Heather Huntington
Enduring Resources Permitting Technician
505-636-9751





Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 447851

QUESTIONS

Operator: ENDURING RESOURCES, LLC 6300 S Syracuse Way Centennial, CO 80111	OGRID: 372286
	Action Number: 447851
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2510536943
Incident Name	NAPP2510536943 KWU 2309-19K RECYCLING FACILITY @ 0
Incident Type	Produced Water Release
Incident Status	Initial C-141 Received
Incident Facility	[fCS1902230487] KWU 2309-19K RECYCLING FACILITY

Location of Release Source	
<i>Please answer all the questions in this group.</i>	
Site Name	KWU 2309-19K RECYCLING FACILITY
Date Release Discovered	04/11/2025
Surface Owner	Federal

Incident Details	
<i>Please answer all the questions in this group.</i>	
Incident Type	Produced Water Release
Did this release result in a fire or is the result of a fire	No
Did this release result in any injuries	No
Has this release reached or does it have a reasonable probability of reaching a watercourse	Yes
Has this release endangered or does it have a reasonable probability of endangering public health	No
Has this release substantially damaged or will it substantially damage property or the environment	No
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No

Nature and Volume of Release	
<i>Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.</i>	
Crude Oil Released (bbls) Details	Not answered.
Produced Water Released (bbls) Details	Cause: Vandalism Pump Produced Water Released: 781 BBL Recovered: 135 BBL Lost: 646 BBL.
Is the concentration of chloride in the produced water >10,000 mg/l	No
Condensate Released (bbls) Details	Not answered.
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Not answered.
Other Released Details	Not answered.
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Not answered.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 447851

QUESTIONS (continued)

Operator: ENDURING RESOURCES, LLC 6300 S Syracuse Way Centennial, CO 80111	OGRID: 372286
	Action Number: 447851
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Nature and Volume of Release (continued)	
Is this a gas only submission (i.e. only significant Mcf values reported)	No, according to supplied volumes this does not appear to be a "gas only" report.
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	Yes
Reasons why this would be considered a submission for a notification of a major release	From paragraph A. "Major release" determine using: (1) an unauthorized release of a volume, excluding gases, of 25 barrels or more; (2) an unauthorized release of a volume that: (b) may with reasonable probability reach a watercourse.
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e. gas only) are to be submitted on the C-129 form.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury.

The source of the release has been stopped	True
The impacted area has been secured to protect human health and the environment	True
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True
All free liquids and recoverable materials have been removed and managed appropriately	True
If all the actions described above have not been undertaken, explain why	Not answered.

Per Paragraph (4) of Subsection B of 19.15.29.8 NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of actions to date in the follow-up C-141 submission. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC), please prepare and attach all information needed for closure evaluation in the follow-up C-141 submission.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

I hereby agree and sign off to the above statement	Name: Heather Huntington Title: Permitting Tech Email: hhuntington@enduringresources.com Date: 04/23/2025
--	--

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 3

Action 447851

QUESTIONS (continued)

Operator: ENDURING RESOURCES, LLC 6300 S Syracuse Way Centennial, CO 80111	OGRID: 372286
	Action Number: 447851
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Site Characterization	
<i>Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date.</i>	
What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs)	Not answered.
What method was used to determine the depth to ground water	Not answered.
Did this release impact groundwater or surface water	Not answered.
What is the minimum distance, between the closest lateral extents of the release and the following surface areas:	
A continuously flowing watercourse or any other significant watercourse	Not answered.
Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	Not answered.
An occupied permanent residence, school, hospital, institution, or church	Not answered.
A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes	Not answered.
Any other fresh water well or spring	Not answered.
Incorporated municipal boundaries or a defined municipal fresh water well field	Not answered.
A wetland	Not answered.
A subsurface mine	Not answered.
An (non-karst) unstable area	Not answered.
Categorize the risk of this well / site being in a karst geology	Not answered.
A 100-year floodplain	Not answered.
Did the release impact areas not on an exploration, development, production, or storage site	Not answered.

Remediation Plan	
<i>Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.</i>	
Requesting a remediation plan approval with this submission	No
<i>The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.</i>	

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 447851

CONDITIONS

Operator: ENDURING RESOURCES, LLC 6300 S Syracuse Way Centennial, CO 80111	OGRID: 372286
	Action Number: 447851
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

CONDITIONS

Created By	Condition	Condition Date
nvez	None	4/23/2025