Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 487161

QUESTIONS

Operator:	OGRID:
BTA OIL PRODUCERS, LLC	260297
104 S Pecos	Action Number:
Midland, TX 79701	487161
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites	s		
Incident ID (n#)	nAPP2212777868		
Incident Name	NAPP2212777868 ROJO 22-25 TANK BATTERY @ 0		
Incident Type	Produced Water Release		
Incident Status	Notification Accepted		
Incident Facility	[fAPP2130123342] Rojo 22 - 25		

Location of Release Source		
Site Name	Rojo 22-25 Tank Battery	
Date Release Discovered	05/06/2022	
Surface Owner	Federal	

Liner Inspection Event Information				
Please answer all the questions in this group.				
What is the liner inspection surface area in square feet	5,300			
Have all the impacted materials been removed from the liner	Yes			
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	07/25/2025			
Time liner inspection will commence	04:00 PM			
Please provide any information necessary for observers to liner inspection	Carmona Resources – 432-813-8988			
Please provide any information necessary for navigation to liner inspection site	32.111021,-103.56406			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 487161

CONDITIONS

Operator:	OGRID:
BTA OIL PRODUCERS, LLC	260297
104 S Pecos Midland, TX 79701	Action Number: 487161
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
ntinker	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	7/21/2025