Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 501118

QUESTIONS

ı	Operator:	OGRID:
ı	OXY USA INC	16696
ı	P.O. Box 4294	Action Number:
ı	Houston, TX 772104294	501118
ı		Action Type:
ı		[NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites	isites		
Incident ID (n#)	nAPP2523232222		
Incident Name	NAPP2523232222 CORRAL WTR TREATMENT FAC @ 0		
Incident Type	Produced Water Release		
Incident Status	Notification Accepted		

Location of Release Source		
Site Name	CORRAL WTR TREATMENT FAC	
Date Release Discovered	08/19/2025	
Surface Owner	State	

Liner Inspection Event Information		
Please answer all the questions in this group.		
What is the liner inspection surface area in square feet	23,000	
Have all the impacted materials been removed from the liner	Yes	
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	09/05/2025	
Time liner inspection will commence	09:30 AM	
Please provide any information necessary for observers to liner inspection	Sample Cell#: 512-496-4197	
Please provide any information necessary for navigation to liner inspection site	GPS Coordinates to site: 32.15403, -103.94595	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 501118

CONDITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	501118
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created		Condition Date
dspar	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	9/2/2025