Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 512050

## **QUESTIONS**

Operator:	OGRID:
MATADOR PRODUCTION COMPANY	228937
One Lincoln Centre	Action Number:
Dallas, TX 75240	512050
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

## QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2527221945
Incident Name	NAPP2527221945 AIRCOBRA TB @ B-12-19S-34E
Incident Type	Oil Release
Incident Status	Initial C-141 Received

Location of Release Source		
Site Name	AIRCOBRA TB	
Date Release Discovered	09/28/2025	
Surface Owner	State	

Liner Inspection Event Information		
Please answer all the questions in this group.		
What is the liner inspection surface area in square feet	3,000	
Have all the impacted materials been removed from the liner	Yes	
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	10/08/2025	
Time liner inspection will commence	08:00 AM	
Please provide any information necessary for observers to liner inspection	Jerry Heidelberg 575-390-3639	
Please provide any information necessary for navigation to liner inspection site	32.680488, -103.511277	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 512050

## **CONDITIONS**

Operator:	OGRID:
MATADOR PRODUCTION COMPANY	228937
One Lincoln Centre	Action Number:
Dallas, TX 75240	512050
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

## CONDITIONS

Created By	Condition	Condition Date
j_touchet	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	10/3/2025