

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 529608

QUESTIONS

Operator:	OGRID:
SOLARIS WATER MIDSTREAM, LLC	371643
9950 WOODLOCH FOREST DR	Action Number:
THE WOODLANDS, TX 77380	529608
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2532128654
Incident Name	NAPP2532128654 1036-49ER BOOSTER @ L-27-23S-31E
Incident Type	Produced Water Release
Incident Status	Initial C-141 Received

Location of Release Source	
Please answer all the questions in this group.	
Site Name	1036-49er Booster
Date Release Discovered	11/16/2025
Surface Owner	Federal

Incident Details	
Please answer all the questions in this group.	
Incident Type	Produced Water Release
Did this release result in a fire or is the result of a fire	No
Did this release result in any injuries	No
Has this release reached or does it have a reasonable probability of reaching a watercourse	No
Has this release endangered or does it have a reasonable probability of endangering public health	No
Has this release substantially damaged or will it substantially damage property or the environment	No
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No

Nature and Volume of Release		
Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.		
Crude Oil Released (bbls) Details	Not answered.	
Produced Water Released (bbls) Details	Cause: Equipment Failure Pump Produced Water Released: 38 BBL Recovered: 20 BBL Lost: 18 BBL.	
Is the concentration of chloride in the produced water >10,000 mg/l	Yes	
Condensate Released (bbls) Details	Not answered.	
Natural Gas Vented (Mcf) Details	Not answered.	
Natural Gas Flared (Mcf) Details	Not answered.	
Other Released Details	Not answered.	
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Not answered.	

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 2

Action 529608

QUESTI	ONS (continued)	
Operator: SOLARIS WATER MIDSTREAM, LLC 9950 WOODLOCH FOREST DR THE WOODLANDS, TX 77380	OGRID:	
QUESTIONS		
Nature and Volume of Release (continued)		
Is this a gas only submission (i.e. only significant Mcf values reported)	No, according to supplied volumes this does not appear to be a "gas only" report.	
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	Yes	
Reasons why this would be considered a submission for a notification of a major release	From paragraph A. "Major release" determine using: (1) an unauthorized release of a volume, excluding gases, of 25 barrels or more.	
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e.	e. gas only) are to be submitted on the C-129 form.	
Initial Response The responsible party must undertake the following actions immediately unless they could create a s	afety hazard that would result in injury	
The source of the release has been stopped	True	
The impacted area has been secured to protect human health and the environment	True	
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True	
All free liquids and recoverable materials have been removed and managed appropriately	True	
If all the actions described above have not been undertaken, explain why	Not answered.	
	ution immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative ed or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of valuation in the follow-up C-141 submission.	
to report and/or file certain release notifications and perform corrective actions for releathe OCD does not relieve the operator of liability should their operations have failed to a	nowledge and understand that pursuant to OCD rules and regulations all operators are require uses which may endanger public health or the environment. The acceptance of a C-141 report by idequately investigate and remediate contamination that pose a threat to groundwater, surface a does not relieve the operator of responsibility for compliance with any other federal, state, or	
I hereby agree and sign off to the above statement	Name: Dalton Walker Title: Environmental Representative Email: Dalton.Walker@westernmidstream.com Date: 11/24/2025	

Sante Fe Main Office Phone: (505) 476-3441

storage site

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 3

Action 529608

QUESTIONS (continued)

Operator:	OGRID:
SOLARIS WATER MIDSTREAM, LLC	371643
9950 WOODLOCH FOREST DR	Action Number:
THE WOODLANDS, TX 77380	529608
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS Site Characterization Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the What is the shallowest depth to groundwater beneath the area affected by the Between 100 and 500 (ft.) release in feet below ground surface (ft bgs) What method was used to determine the depth to ground water NM OSE iWaters Database Search Did this release impact groundwater or surface water What is the minimum distance, between the closest lateral extents of the release and the following surface areas: A continuously flowing watercourse or any other significant watercourse Between 1 and 5 (mi.) Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark) Between 1 and 5 (mi.) An occupied permanent residence, school, hospital, institution, or church Greater than 5 (mi.) A spring or a private domestic fresh water well used by less than five households Greater than 5 (mi.) for domestic or stock watering purposes Any other fresh water well or spring Greater than 5 (mi.) Incorporated municipal boundaries or a defined municipal fresh water well field Greater than 5 (mi.) Between 1 and 5 (mi.) A subsurface mine Greater than 5 (mi.) An (non-karst) unstable area Between 1 and 5 (mi.) Categorize the risk of this well / site being in a karst geology A 100-year floodplain Greater than 5 (mi.)

Remediation Plan		
Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.		
Requesting a remediation plan approval with this submission	No	
The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.		

No

Did the release impact areas not on an exploration, development, production, or

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 529608

CONDITIONS

Operator:	OGRID:
SOLARIS WATER MIDSTREAM, LLC	371643
9950 WOODLOCH FOREST DR	Action Number:
THE WOODLANDS, TX 77380	529608
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

CONDITIONS

Created By	Condition	Condition Date
michael.buchanan	The Initial C141 is approved. A remediation closure, site characterization plan OR remediation work plan is due to the OCD no later than 90-days after the discovery of the release. Submit the next report to OCD no later than 02/20/2026.	11/26/2025