



# Certificate of Analysis

Number: 6030-25050052-001A

**Artesia Laboratory**  
 200 E Main St.  
 Artesia, NM 88210  
 Phone 575-746-3481

Alex Batista  
 Taprock  
 602 Park Point Drive  
 Ste. 200  
 Golden, CO 80401

Station Name:	High Life Sales Check	Report Date:	05/08/2025
Station Number:	6060025	Sampled By:	Dustin Sharp
Sample Point:	Meter Run	Sample Of:	Gas
Formation:	Spot	Sample Type:	Spot
County:	Lea	Sample Conditions:	67 psig, @ 89.9 °F Ambient: 84 °F
Type of Sample:	Spot-Cylinder	Sample Date:	05/01/2025 02:15
Heat Trace Used:	N/A	Received Date:	05/02/2025
Sampling Method:	Fill and Purge	Login Date:	05/02/2025
Sampling Company:	SPL	Effective Date:	05/01/2025
Cylinder No:	1111-007068	Flow Rate:	222.9509 MSCFD
Instrument:	70142339 (Inficon GC-MicroFusion)	Sampling Method:	
Last Inst. Cal.:	05/05/2025 07:02:24	Heating Method:	
Analyzed:	05/08/2025 07:50:36 by CDW	Method:	GPA-2261M

## Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.73 psia	
Hydrogen Sulfide	0.000	0.000	0.000		GPM TOTAL C2+ 2.540
Nitrogen	1.507	1.533	2.313		GPM TOTAL C3+ 1.097
Methane	88.096	89.644	77.459		GPM TOTAL iC5+ 0.510
Carbon Dioxide	0.189	0.192	0.455		
Ethane	5.288	5.381	8.715	1.443	
Propane	1.382	1.406	3.339	0.388	
Iso-butane	0.160	0.163	0.510	0.053	
n-Butane	0.453	0.461	1.443	0.146	
Iso-pentane	0.133	0.135	0.525	0.049	
n-Pentane	0.177	0.180	0.699	0.065	
Hexanes Plus	0.889	0.905	4.542	0.396	
	98.274	100.000	100.000	2.540	

<b>Calculated Physical Properties</b>	<b>Total</b>	<b>C6+</b>
Relative Density Real Gas	0.6425	3.2176
Calculated Molecular Weight	18.57	93.19
Compressibility Factor	0.9973	

**GPA 2172 Calculation:**

**Calculated Gross BTU per ft<sup>3</sup> @ 14.73 psia & 60°F**

Real Gas Dry BTU	1121	5141
Water Sat. Gas Base BTU	1102	5052
Ideal, Gross HV - Dry at 14.73 psia	1118.0	5141.1
Ideal, Gross HV - Wet	1098.5	5051.6
Net BTU Wet Gas - real gas	996	

**Comments:** low pressure not enough to rerun  
 H2S Field Content: 0 %

*Mostaq Ahamed*

Hydrocarbon Laboratory Manager

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated. The test results apply to the sample as received.

FLARING SUMMARY

Battery	Date	Total Flare Vol (mcf)	Hrs Flared	Start	End

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

DEFINITIONS

Action 554058

**DEFINITIONS**

Operator: TAP ROCK OPERATING, LLC 1700 Lincoln St Denver, CO 80203	OGRID: 372043
	Action Number: 554058
	Action Type: [C-129] Venting and/or Flaring (C-129)

**DEFINITIONS**

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 554058

**QUESTIONS**

Operator: TAP ROCK OPERATING, LLC 1700 Lincoln St Denver, CO 80203	OGRID: 372043
	Action Number: 554058
	Action Type: [C-129] Venting and/or Flaring (C-129)

**QUESTIONS**

<b>Prerequisites</b>	
<i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i>	
Incident Well	Unavailable.
Incident Facility	[fAPP2511254334] High Life Upslope Fed Com CTB

<b>Determination of Reporting Requirements</b>	
<i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i>	
Was this vent or flare caused by an emergency or malfunction	No
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.
<i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i>	
Was there <b>at least 50 MCF</b> of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of <b>ANY</b> liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or within 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

<b>Equipment Involved</b>	
Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

<b>Representative Compositional Analysis of Vented or Flared Natural Gas</b>	
<i>Please provide the mole percent for the percentage questions in this group.</i>	
Methane (CH4) percentage	90
Nitrogen (N2) percentage, if greater than one percent	2
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0
<i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i>	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 554058

**QUESTIONS (continued)**

Operator: TAP ROCK OPERATING, LLC 1700 Lincoln St Denver, CO 80203	OGRID: 372043
	Action Number: 554058
	Action Type: [C-129] Venting and/or Flaring (C-129)

**QUESTIONS**

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	12/24/2025
Time vent or flare was discovered or commenced	12:01 AM
Time vent or flare was terminated	11:59 PM
Cumulative hours during this event	1

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	<i>Not answered.</i>
Natural Gas Flared (Mcf) Details	<i>Not answered.</i>
Other Released Details	Cause: Normal Operations   Tank (Any)   Natural Gas Flared   Released: 75 Mcf   Recovered: 0 Mcf   Lost: 75 Mcf.
Additional details for Measured or Estimated Volume(s). Please specify	<i>Not answered.</i>
Is this a gas only submission (i.e. only significant Mcf values reported)	<b>Yes, according to supplied volumes this appears to be a "gas only" report.</b>

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	No
Was notification of downstream activity received by this operator	<i>Not answered.</i>
Downstream OGRID that should have notified this operator	<i>Not answered.</i>
Date notified of downstream activity requiring this vent or flare	<i>Not answered.</i>
Time notified of downstream activity requiring this vent or flare	<i>Not answered.</i>

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	The location experienced normal operations and the flaring can be attributed to flash gas/tank vapors coming off the tank and going to low pressure flare.
Steps taken to limit the duration and magnitude of vent or flare	Standard PM. Worked with vendor to coordinate service time and minimize downtime.
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Standard PM. No way to avoid periodic downtime for maintenance/repairs to address unforeseen issues.



Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 554058

**ACKNOWLEDGMENTS**

Operator: TAP ROCK OPERATING, LLC 1700 Lincoln St Denver, CO 80203	OGRID: 372043
	Action Number: 554058
	Action Type: [C-129] Venting and/or Flaring (C-129)

**ACKNOWLEDGMENTS**

<input checked="" type="checkbox"/>	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a <b>complete</b> C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
<input checked="" type="checkbox"/>	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
<input checked="" type="checkbox"/>	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
<input checked="" type="checkbox"/>	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
<input checked="" type="checkbox"/>	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 554058

**CONDITIONS**

Operator: TAP ROCK OPERATING, LLC 1700 Lincoln St Denver, CO 80203	OGRID: 372043
	Action Number: 554058
	Action Type: [C-129] Venting and/or Flaring (C-129)

**CONDITIONS**

Created By	Condition	Condition Date
mlaruecdh	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	2/15/2026