

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 586318

**QUESTIONS**

|  |  |
|--|--|
| Operator:<br>HILCORP ENERGY COMPANY<br>1111 Travis Street<br>Houston, TX 77002 | OGRID:<br>372171   |
|  | Action Number:<br>586318   |
|  | Action Type:<br>[NOTIFY] Notification Of Liner Inspection (C-141L) |

**QUESTIONS**

|                      |  |
|----------------------|--|
| <b>Prerequisites</b> |  |
| Incident ID (n#)     | nAPP2602822415                                       |
| Incident Name        | NAPP2602822415 W.W. WEATHERLY BATTERY @ 30-025-37537 |
| Incident Type        | Oil Release  |
| Incident Status      | Initial C-141 Approved                               |
| Incident Well        | [30-025-37537] WEST BLINEBRY DRINKARD UNIT #094      |

|                                   |                        |
|-----------------------------------|------------------------|
| <b>Location of Release Source</b> |                        |
| Site Name                         | W.W. WEATHERLY BATTERY |
| Date Release Discovered           | 01/27/2026             |
| Surface Owner                     | State                  |

|   |                                       |
|---|---------------------------------------|
| <b>Liner Inspection Event Information</b>   |                                       |
| <i>Please answer all the questions in this group.</i>   |                                       |
| What is the liner inspection surface area in square feet  | 6,000                                 |
| Have all the impacted materials been removed from the liner   | Yes                                   |
| Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC | 05/28/2026                            |
| Time liner inspection will commence   | 11:00 AM                              |
| Please provide any information necessary for observers to liner inspection                              | Alex Ferrell - aferrell@ensolum.com   |
| Please provide any information necessary for navigation to liner inspection site                        | GPS coordinates: 32.47973, -103.18231 |

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oecd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 586318

**CONDITIONS**

|  |  |
|--|--|
| Operator:<br>HILCORP ENERGY COMPANY<br>1111 Travis Street<br>Houston, TX 77002 | OGRID:<br>372171   |
|  | Action Number:<br>586318   |
|  | Action Type:<br>[NOTIFY] Notification Of Liner Inspection (C-141L) |

**CONDITIONS**

| Created By | Condition  | Condition Date |
|------------|--|----------------|
| shyde      | Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted. | 5/19/2026      |