

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 587153

QUESTIONS

Operator: ONEOK Delaware Gathering, L.L.C. 1722 Routh Street Dallas, TX 75201	OGRID: 373760
	Action Number: 587153
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2605268430
Incident Name	NAPP2605268430 ALAMO COMPRESSOR STATION @ FAPP2123137223
Incident Type	Fire
Incident Status	Initial C-141 Approved
Incident Facility	[fAPP2123137223] ALAMO COMPRESSOR STATION

Location of Release Source	
Site Name	Alamo Compressor Station
Date Release Discovered	02/21/2026
Surface Owner	Federal

Liner Inspection Event Information	
<i>Please answer all the questions in this group.</i>	
What is the liner inspection surface area in square feet	2,500
Have all the impacted materials been removed from the liner	Yes
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	05/22/2026
Time liner inspection will commence	08:00 AM
Please provide any information necessary for observers to liner inspection	This was a gas release, no remediation is required. No liner inspection is required. The fire was determined to have no impact on the soils below the elevated equipment. Due to no fluid being released and no impact from the fire affecting the soil, no remediation, reclamation, or revegetation will be required. We are requesting full site closure and a variance to the reclamation & revegetation portion of the NMAC 19.15.29.13 as there was no impact to the soils below this equipment. Furthermore, per normal oilfield operation, this site will be reclaimed and vegetated during P/A activities.
Please provide any information necessary for navigation to liner inspection site	911 Address: 563 Cotton Draw Rd, Jal, NM 88252 •Latitude: 32.114597 Longitude: -103.586918

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 587153

CONDITIONS

Operator: ONEOK Delaware Gathering, L.L.C. 1722 Routh Street Dallas, TX 75201	OGRID: 373760
	Action Number: 587153
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
dunderwood	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	5/20/2026